

# Site Investigation Report

Auger Ref:



## Job Information

Client	Crawford & Co
Client ref	
Visit date	04/09/2025
Report date	17/09/2025

## Job Summary

- ✓ CCTV survey undertaken. [Read more.](#)
- ! Drainage repairs required. [Read more.](#)



# Job Information

## Overview

### Brief

Auger were commissioned by Crawford & Co to undertake a site investigation and CCTV inspection of the underground drainage within the area of concern (AOC) at the property.

## Findings

### Trial Hole Findings

#### Trial Hole 1

TH1 was completed in the proposed location and revealed the footing. Soil and root samples were taken.

### Drain Survey

We carried out a CCTV survey of the below ground drainage system, our findings of which are as follows:

#### Line 1 - From MH1 upstream

Our survey of line 1 revealed no significant defects to the pipework on this line which could be allowing an escape of water.

#### Line 2 - From MH1 upstream

Our survey of line 2 revealed fractures.

#### Line 3 - From MH1 downstream

Our survey of line 3 revealed root ingress, joint displacements and cracking.

#### Line 4 - From RWG1 downstream to Line 3

Our survey of line 4 revealed joint displacements.

#### Line 5 - From RWG2 downstream to MH1

Our survey of line 5 revealed joint displacements.

## Recommendations

It is recommended that the following repairs are carried out to prevent an escape of water from the system:

### Line 2

Install a 100mm patch liner approximately 5.3m upstream of MH1.

### Line 3

Install 6m of 100mm liner directly downstream of MH1.

### Line 4

Excavate and replace RWG1 and 1m of 100mm pipework including a branch connection at a depth no greater than 1.0m through block paving.

### Line 5

Excavate and replace RWG2 and 1m of 100mm pipework at a depth no greater than 1.0m through block paving.

## Refer Back to Client

Auger have not allowed or will not be held responsible for any alteration or modification to the above ground drainage following the removal of the existing gully and reinstatement of a new gully. The customer must ensure that the above ground drainage correctly expels into the gully pot and avoids overcrowding the gully with numerous downpipes which could lead to the gully overflowing.

During the clean-up/reinstatement process we will endeavour to leave the area we are working in clean and tidy and as close to how we found it as possible. There will always be an element of general debris/mud/waste that will build up in the area which cannot be prevented. There may however be elements of this process that are outside our remit i.e., Repainting or cleaning. If this is the case, then we will need to speak to the customer's insurers to help in this regard.

We will now refer the claim back to the client in order to progress the claim.

*Once repairs have been undertaken the customer should ensure the drainage system is periodically inspected in the future for any deterioration and kept free flowing / free of blockages. Any damage noted during future inspections should be repaired immediately in accordance with current Building Regulations.*

*With any repair process, complications and unforeseen circumstances can arise. These scenarios will be reported whilst on-site and could potentially cause an increase in repair costs and inconvenience.*

*Where any excavation reinstatement of the surface is required, the reinstatement will always attempt to match the previous surface patterns and colouring, however we cannot guarantee an exact match.*

## Repair Caveats

*If any of the above lining recommendations fail then excavation and replacement of the pipework would be required. This would severely increase the cost of repairs and would provide greater inconvenience to the residents. The relining of a severe joint displacement is normally unadvised due to the potential for complications in the future.*

*Recommendations have been made to reline or patch reline sections of the drainage system at the property. This process combines a number of chemicals in a resin, which then harden in a fibreglass matting to create a new section of drain within the original. The reaction creates **a strong smell which can linger for up to 72 hours** once works are completed - this is not harmful. It is recommended that any areas where smells are experienced are kept well ventilated until the odour subsides.*

*The above recommendations allow for the replacement of gullies & connected underground drainage only. The insured should be made aware that the aesthetic appearance of this gully may be different from what is currently in place.*

# Photographs

## Trial Hole 1

Fig 1.1: Trial Hole 1 Location




Fig 1.2: Trial Hole 1 Footing



## CCTV Stills

Fig 2.1: Line 4 Displacement





Fig 2.2: Line 2 Fracture



## Site Photos

Fig 3.1: MH1



## CCTV Survey – Inspection Listings (WRc Guidelines Applied)

LINE1	
Direction	Upstream
Pipe Size (mm)	
Pipe Material	
From	MH1
Depth (m)	OUTFALL
To	

1.9m	Connection
2.4m	Connection
4.3m	Junction
4.3m	Finish of Survey Length (OUT OF AOC)

#### LINE2

<b>Direction</b>	Upstream	<b>From</b>	MH1
<b>Pipe Size (mm)</b>		<b>Depth (m)</b>	OUTFALL
<b>Pipe Material</b>		<b>To</b>	

4.4m	Finish of Survey Length (OUT OF AOC )
5.2m	Fracture - Multiple
5.2m	H

#### LINE3

<b>Direction</b>	Downstream	<b>From</b>	MH1
<b>Pipe Size (mm)</b>		<b>Depth (m)</b>	OUTFALL
<b>Pipe Material</b>		<b>To</b>	

3.3m	Crack - Circumferential
5.7m	Crack - Circumferential
6.0m	Connection (RWG1 )
7.8m	Finish of Survey Length (OUT OF AOC)

#### LINE4


<b>Direction</b>	Downstream	<b>From</b>	RWG1
<b>Pipe Size (mm)</b>		<b>Depth (m)</b>	LINE3
<b>Pipe Material</b>		<b>To</b>	

0.1m	Joint Displacement - Medium
0.5m	Joint Displacement - Large
0.7m	Finish of Survey Length (LINE3)

#### LINE5

<b>Direction</b>	Downstream	<b>From</b>	RWG2
<b>Pipe Size (mm)</b>		<b>Depth (m)</b>	LINE2
<b>Pipe Material</b>		<b>To</b>	

0.1m	Displacement (medium)
0.4m	Finish of Survey Length (LINE2)



## FRONT OF PROPERTY

This drawing should be used for diagrammatic purposes only. Auger are not responsible or liable for any 3rd party works undertaken using the details outlined in this drawing. Confirmation of the drainage configuration can only be confirmed by excavation or detailed technical survey.

LEGEND	
	= Manhole (MH)
	= Inspection Chamber (IC)
	= Inspection Point (IP)
	= Blockage / Collapse
	= Soil Vent Pipe (SVP) / WC
	= Combined Waste Gully (CWG) / Foul Waste Gully (FWG)
	= Rainwater Gully (RWG)
	= Rainwater Pipe (RWP)
	= Lines not to be repaired
	= Lines to be repaired
	= Assumed water mains feed
	= Walls
	= Fences
	= Building Outline
	= Trial hole
	= Borehole
	= Direction of flow
	= Gate / Door
	= Shrubs / Bush
	= Hedge
	= Tree
	= Steps



# Trial Hole Log No.1

Location: Left hand side Bay window

Job Ref: \_\_\_\_\_

Depth (m)	Symbolic Log	Strata Description	Insitu Tests		Soil Sample	Root Sample
			SV(19)			
0.0		Ground Level Block Paving Brickwork Concrete				
0.5		Very dry very stiff brown fine gravelly silty CLAY	98kpa		Soil @ 0.5m	Root @ 0.5m
1.0			102kpa		Soil @ 1m	Root @ 1m
1.5			104kpa		Soil @ 1.5m	
2.0			112kpa		Soil @ 2m	
2.5		Dry very stiff brown silty CLAY	130kpa		Soil @ 2.5m	
3.0		TRIAL HOLE TERMINATED	122kpa			

Unit 3 & 4,  
 Heol Aur,  
 Dafen Ind Estate,  
 Dafen  
 Llanelli,  
 Carmarthenshire,  
 SA14 8QN

**\*The testing results contained within this report have been performed by GSTL a UKAS accredited laboratory on behalf of Auger.**

**Auger House,  
 Cross Lane,  
 Wallasey,  
 Wirral,  
 CH45 8RH**

**Summary Of Claim Details**


<b>Policy Holder</b>	
<b>GSTL Job Reference</b>	
<b>SI Date</b>	
<b>Issue Date</b>	04/09/2025
<b>Report Date</b>	04/09/2025
<b>Auger Reference</b>	
<b>Insurance Company</b>	NFU Mutual
<b>LA Claim Reference</b>	
<b>LA Co. Reference</b>	Crawford & Co

This certificate is issued in accordance with the accreditation requirements of the United Kingdom Accreditation Service. The results reported herein relate only to the material supplied to the laboratory. This certificate shall not be reproduced except in full, without the prior written approval of the laboratory.


Checked and approved	26/09/2025	
----------------------	------------	--







PLASTICITY CHART FOR CASAGRANDE CLASSIFICATION  
BS 5930:1999+A2:2010



Modified Plasticity Index (PI) <10 : Non Classified  
 Modified PI = 10 to <20 : Low volume change potential (LOW VCP)  
 Modified PI = 20 to <40 : Medium volume change potential (Med VCP)  
 Modified PI = 40 or greater : High volume change potential (HIGH VCP)

The Atterberg Limits May also be used to classify the volume change potential of fine soils using the National House building system, as given in the NHBC's Standards Chapter 4.2 (2003) "Building Near Trees"

Test Operator  
 Jason Smith



# Richardson's Botanical Identifications

Root identification  
Vegetation surveys  
Tree/Building investigations  
Plant taxonomy

**Dr Ian B K Richardson**  
*BSc, MSc, PhD, MRSB, FLS*

**James Richardson**  
*BSc (Hons. Biology)*

## **Auger Solutions**

**Auger House**

**Cross Lane**

**WALLASEY**

**Wirral CH45 8RH**

**Enterprise House**  
**49-51 Whiteknights Road**  
**Reading**  
**RG6 7BB**

**Tel:**

**E-mail:**

**Web:** [www.botanical.net](http://www.botanical.net)

*Your ref:*

*Our ref:*

18/09/2025

Dear Sirs

### **Root ID**

The samples you sent in relation to the above on 04/08/2025 have been examined. Their structures were referable as follows:

<b>TH1, 0.5m</b>		
6 no.	Examined root: FRAXINUS (Ash).	Alive, recently*.
<b>TH1, 1.0m</b>		
4 no.	Examined root: FRAXINUS (Ash).	Dead*.
3 no.	Unfortunately all with insufficient cells for identification.	

Click here for more information: [FRAXINUS](#)

I trust this is of help. Please call us if you have any queries; our Invoice is enclosed.

Yours faithfully

Dr Ian B K Richardson

\* Based mainly on the Iodine test for starch. Starch is present in some cells of a living woody root, but is more or less rapidly broken down by soil micro-organisms on death of the root, sometimes before decay is evident. This result need not reflect the state of the parent tree.

\*\* Try out our web site on [www.botanical.net](http://www.botanical.net) \*\*