



General view south end



General view North End



OK



OK



OK



Unknown



OK



OK



OK



OK



OK



OK



OK



OK



OK




Odd detail in the capping stones adjacent to the post. Three capping stones have been mortared in a set back position. Appears OK.



OK



OK



Unknown



Unknown



Unknown



Unknown



South end of wall



OK



OK



OK



OK



OK



OK



OK