

Your ref 084665694

Our ref 09501GLOB

Geo-Serv Limited
17 Hoveden Road
London NW2 3XE

tel: **020 8208 0343**

email: **mon@geo-serv.com**

Subsidence
Monitoring
Services



GEO-SERV

360Globalnet Ltd
Bramley House,
Bramley Road,
Long Eaton,
NG10 3SX

Issue date: 28/10/2024

Monitoring visit **7** of **7**

Monitoring Plus Report

Owners name	Mr Gavin Harper	Suspected cause	to be advised	Monitoring type	levels & cracks
Address	Field House, Wood Street Skelmanthorpe, Huddersfield West Yorkshire HD8 9BN	Principal area of damage	to be advised	Installed	14/08/2023
		Damage category	to be advised	Frequency (weeks)	8.7
		Surface geology	to be advised	Completion date	
				Status	completed
Comment	Feedback from last visit				
Max move 4.2 mm	no feedback for this visit				
Focal area Pts 4r, 5, 6, 7, 8, 9, 10,					
28/10/2024- Instructed visits completed.					
Sketch showing location of monitoring points					
Front Elevation					

Level Monitoring Results



Survey:	1		2		3		4		5	
By:	BL		BL		BL		Ben		Russ	
Date:	14/08/2023		11/12/2023		19/02/2024		22/04/2024		21/06/2024	
Point ID	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm
1	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0
2	223.52	0.0	224.08	0.6	223.74	0.2	223.39	-0.1	224.12	0.6
3r	-492.79	0.0	-491.90	0.9	-491.36	1.4	-491.04	1.7	-492.77	0.0
4r	-616.20	0.0	-615.58	0.6	-614.98	1.2	-614.72	1.5	-616.56	-0.4
5	-2034.52	0.0	-2033.24	1.3	-2032.63	1.9	-2031.12	3.4	-2032.55	2.0
6	-2185.31	0.0	-2183.33	2.0	-2182.75	2.6	-2181.11	4.2	-2182.72	2.6
7	-2111.80	0.0	-2110.72	1.1	-2110.54	1.3	-2110.11	1.7	-2110.85	1.0
8	-2113.48	0.0	-2112.24	1.2	-2112.66	0.8	-2112.12	1.4	-2112.43	1.1
9	-2133.48	0.0	-2132.33	1.2	-2132.08	1.4	-2131.62	1.9	-2132.09	1.4
10	-654.89	0.0	-653.99	0.9	-653.05	1.8	-653.04	1.8	-653.52	1.4

closing error (mm) -0.18 0.20 0.21 -0.39 0.35

Survey:	6		7		8		9		10	
By:	Ben		Ben		#N/A		#N/A		#N/A	
Date:	20/08/2024		28/10/2024		#N/A		#N/A		#N/A	
Point ID	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm
1	1000.00	0.0	1000.00	0.0		#N/A		#N/A		#N/A
2	223.80	0.3	224.02	0.5		#N/A		#N/A		#N/A
3r	-493.33	-0.5	-493.01	-0.2		#N/A		#N/A		#N/A
4r	-617.76	-1.6	-617.43	-1.2		#N/A		#N/A		#N/A
5	-2033.66	0.9	-2032.60	1.9		#N/A		#N/A		#N/A
6	-2184.02	1.3	-2182.31	3.0		#N/A		#N/A		#N/A
7	-2111.51	0.3	-2108.30	3.5		#N/A		#N/A		#N/A
8	-2113.41	0.1	-2110.69	2.8		#N/A		#N/A		#N/A
9	-2133.58	-0.1	-2130.80	2.7		#N/A		#N/A		#N/A
10	-655.32	-0.4	-651.39	3.5		#N/A		#N/A		#N/A

closing error (mm) 0.07 0.39 #REF! #REF! #REF!

Precise level monitoring related to Point 1



Photos from visit on 28/10/2024

