Proposed Guttering Replacement at 4 Thornhill Road
Existing and Proposed Photos



Photo 1 – Existing guttering to main building, timber profile guttering (to be replaced) above timber fascia board (to remain in place).



Photo 2 – Timber profile guttering to rear single storey area of building.

Proposed Guttering Replacement at 4 Thornhill Road
Existing and Proposed Photos



Photo 3 – Proposed replacement aluminium guttering, Yeoman Rainguard ‘MOG SL Gutter’.