

(NE3259) Land Adjacent to 20 Bank View, Birkenshaw, West Yorkshire

Sub Surface

Wed 03/04/2019 17:11

John

I have looked at our report and your proposal is acceptable. The essential part is that the rotary piles are taken down into the intact rock strata below the mineworkings.

Regards

Andy Parker

Principal Geotechnical Engineer

For and on behalf of

Sub Surface Consultants Ltd**CHECK OUT OUR BRAND NEW REDEVELOPED WEBSITE!**

Want to appear higher on Google? Join our Website Link Building Campaign!

▷ link your website with Sub Surface's.

Sent: 03 April 2019 11:46

Subject: Re: (NE3259) Land Adjacent to 20 Bank View, Birkenshaw, West Yorkshire

Hi Andy, David,

Please see attached report that was prepared back in 2014. Also attached are the house designs, pile layout design and specification of works/quotation for the works.

We have decided to go with a drill and case rotary pile to beyond 15m depth which seems to be deeper than any voids or coal seams.

Please can you advise if this is acceptable in these circumstances?

Regards

John

Get [Outlook for iOS](#)

From: Sub Surface

Subject: (NE3259) Land Adjacent to 20 Bank View, Birkenshaw, West Yorkshire

John

6/5/2019

Mail – John Fawthrop - Outlook

Please find attached our interpretative report for the above site. A paper and CD copy of the report will be in this evening's post.

Regards

Andy Parker

Principal Geotechnical Engineer

For and on behalf of

Sub Surface Limited