

GARAGE

BORDER BETWEEN 347 DRUB LANE
AND 73 LATHAM LANE

HATCHED AREAS
AFFECTED BY TREE ROOTS

EVIDENCE OF
FURTHER LIFTING

GATEWAY TO 347 DRUB LANE

POSITION OF
TREE IN A
RAISED BED

GATEWAY TO 73 LATHAM LANE

MAIN IMPACT

← LATHAM

LANE →