

PLAN 1.

B
O
U
N
D
A
R
Y
W
A
L
L

T4 WORK
REQUIRED

T3

T2 WORK
REQUIRED

T1

NO WORK

NO WORK
REQUIRED
ROWAN
TREE

PATIMAN

ST JOHN'S CHURCH

CLECKHEATON.

MAIN DOOR ENTRANCE.

MAIN GATE
ENTRANCE.

T2, T4 overhanging branches
in contact with Church roof
in windy weather - Potential
for damage to external roof
resulting in internal damage.