Paul Martin
West End Joiners & Builders Ltd

785 - ST PAULS, MIRFIELD

1of3 Delap/Condition Survey documenting current condition of the LEFT HAND SIDE FOOTPATH from Junction of HUDDERSFIELD RD up ST PAULS RD to property identified as NO7

Tuesday 22 October 2024

Client CONNECT HOUSING

91 Issues Identified



LOCATION

1 / PHARMACY HUDDERSFIELD RD

2

3



4

5

6

7

8

9

10

11

12

13

14

15

JUSTMYLOOK
FUELLING THE UK'S BEAUTY OBSESSION
13:11 22/10/2024

16

JUSTMYLOOK
FUELLING THE UK'S BEAUTY OBSESSION
13:11 22/10/2024

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48 / SITE ENTRANCE

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89



90 / NO 7 ST PAULS ROAD