Caption taken from RAMs regarding dust suppression

1.5	Use of Tools	Personnel involved in the task Personnel in the vicinity	Overheating of equipment, faulty guarding/equipment, and incompetent person. Hearing damage. HAVS Exhaust Fumes Ejection Entanglement with moving parts Live Services Silica dust	3	3	9	Tools must be subject to a visual pre-use check by the operator. Operatives must ensure that they check for defects and for the presence of protective devices. Equipment with defects must be de-commissioned and the defect reported to the site foreman. Operatives are not permitted to carry out maintenance on equipment. If there is a presence of silica dust due to operation of the power tool, RPE must be worn and water suppression must be carried out by a second operative during the task. A minimum of FFP3 dust mask used with replaceable cartridges. RPE to be fitted to the individual. Operatives to be trained in the correct use of RPE and face fit test certs forwarded to PRINCIPAL CONTRACTOR for their records. Hearing protection must be worn at all times if equipment produces excessive noise. This includes those working in the area that are susceptible to hearing damage. Hearing protection will be made available in areas where noise production is 80dB or over. Hearing protection must be worn in areas where noise production is 85dB or over. Hearing protection provided must not bring noise levels below 70dB.	1	3	3