



Plotted by Annice Fuller on 10/11/2023 at 0.114889 plot scale

0,0 Microfilm Registration Marks

Existing, repaired and re-used equipment



New surfacing and features proposed



- ① New swing seats with swing frames painted
- ② Climbing frame repaired - platforms and net
- ③ Existing roundabout
- ④ Existing single point swing
- ⑤ Existing climbing frame
- ⑥ Existing zipwire
- ⑦ Existing benches painted and re-used
- ⑧ Existing sign removed and new installed
- ⑨ Existing MUGA
- ⑩ Path from MUGA not extended
- ⑪ One replacement litter bin provided
- ⑫ New sand carpet surface over existing
- ⑬ New grass mat surface
- ⑭ Gradation of ground and new turf required
- ⑮ Black wetpour rubber crumb surface
- ⑯ Boulders to play and sit on

NOTES

This scheme provides a new safety surface to all existing equipment and includes the repair of a number of play items.

It will remove the failing wooden posts, reuse the existing benches, and ensure a new safety surface beneath all items of equipment.

Consideration of levels is important around the roundabout and may result in a gentle gradient across the surface between the roundabout and swings.

Please see the accompanying image sheet for suggestions of additional items that could be included with additional funds.



Landscape, Flint Street, Huddersfield HD1 6LG

Client
PARKS & OPEN SPACES
Playable Spaces

Project
Staincliffe Park
Play Area

Drawing Title
Draft design
Option 1

A3	Scale 1:200	Drawn AF 14.07.23	Checked
	<small>Cad Ref v:\groups\landscape\architects\projects\lad\lad.549.staincliffe.park\4.drawings\staincliffe.design.with.topo.base.af</small>		

Project No. LAD. 549	Drawing No. Sk01	Revision Rev 1
-------------------------	---------------------	-------------------