


Do not scale this drawing. All dimensions must be checked/verified on site. If in doubt ask.

This drawing is to be read in conjunction with all relevant technicalities, engineering and specialist drawings and specifications.

All dimensions in millimeters unless noted otherwise. All levels in metres unless noted otherwise.

Any discrepancies noted on site are to be reported to the Engineer immediately.



Issues & Revisions	Date	Details of issues / Revisions	Drawn	Final
	13.04.16	ISSUED FOR SECTION 278 AGREEMENT	LA	NA
	01.04.16	ISSUED FOR SECTION 278 AGREEMENT	LA	NA

BWB

United States | 1-800-236-8673
Canada | 905-477-9643

☐ Birmingham | 0121 253 3522
☒ Leeds | 0113 250 8000
☐ London | 020 7234 8122
☐ Manchester | 0161 235 4290
☐ Nottingham | 0115 954 1100

www.bwbconsilience.com



BAM Construction Ltd.

Royds Hall Community School

Section 278
Longwood Road, Clough
Lane Victory Avenue &
Luck Lane Layout

Acids	As Shown	Dawn	Lacher
Alkalis	Al	Revised	W. J. Webb

Drawing No. LDH/2129/721	Revision P2
------------------------------------	-----------------------



ORIGINATOR:

Scheme Title:

Scheme No:

COMPLETION DATE

File:

PI target date for SA3
(4 weeks after completion date)

CHANGES TO DESIGN ON SITE / OTHER COMMENTS

Stage 3

Drawing No.

SUMMARY OF ACTIONS REQUIRED

AIP Officer Comments

(Check Aide Memoir)

AIP sign	Date

DESIGN TEAM RESPONSE / ACTION TAKEN

ORIGINATOR:

Scheme Title:

Scheme No:

PROGRESS

MW	GHW	SP	OTHER

File:

Audit	Auditor			Logged by		Group Engineer		Logged by	
	Print Name	Initial	Date Complete	Initial	Date	Approval	Date	Initial	Date
Stage 1/2	Jas Chavre	JCW	18/4/16	JCW	18/4/16	PA	18/4/16	JCW	18/4/16
Stage 3									

Stage 1/2

Drawing No. LDH/2129/721-P2

SUMMARY OF ACTIONS REQUIRED

With regard to suggested School Way Clear markings - these are only suitable where children cross in numbers. The restriction on Victory Ave (if provided) would probably be No Waiting / No Loading. Length to be determined, heavy in mind parking will be displaced elsewhere.

AIP Officer Comments

(Check Aide Memoir)

AIP sign	Date
JCW	18/4/16

DESIGN TEAM RESPONSE / ACTION TAKEN

SAFETY MEMOS COMMENTS NOTED. FURTHER INVESTIGATION INTO ROADWORKS AND TUE OF WORKING TO UNDERTAKE ONCE THE SCHOOL IS IN OPERATION