

GG119 - F4 Road Safety Audit Decision Log
Prepared in response to Stage 1 Road Safety Audit by M
Planning Application 20233/91835 at location Cliff Hollin

RSA Problem No	RSA Problem
Problem 1	During the site visit it was noted that the post and rail fence along the site frontage is incomplete. Also, the footway entering the site runs along an embankment. The drawings do not show if the post and rail fence will be completed and does not show any fencing along the footway to protect pedestrians from the embankment. A lack of suitable fencing will increase both the risk of pedestrians and cyclists falling down unprotected embankments.

Ieraki Alliance Ltd, dated 28/11/24
s Lane, East Bierley, BD12 7ET

RSA Recommendation	Design Organisation Response
Provide appropriate fencing both along the site frontage and the access road.	Appropriate fencing will be added to the architects drawings.

Overseeing Organisation Response	Agreed RSA Action
1.2m High fencing should be provided adjacent to pedestrian/cycle route along the site frontage. This should be identified on the AMA site access plans (and also the architects plans). For the footway on the outside of the bend on entry to the site, a similar fence should be provided, and identified on the architects site plans.	Provide 1.2m high fencing over a distance of 10m at either side of the site access.