

Further comments by applicant's agent in **green**, by email 04/03/2026, in response to comments by KC LLFA:

The flow control device should have a replacement of the neoprene seal if the flow control must be removed for blockages at any point in the future.

The flow control device does have replacement neoprene seals.

We advise the planning officer that confirmation is required that the design for the tank is FP McCann with submitted drawings, and has not been changed to crate storage which cannot be maintained as described in the report. Once this is done the condition CAN be discharged without further consultation to the LLFA”

The tank is as described and hasn't been changed.