

**Batley, Birstall and Birkenshaw TRO No 6 2022**  
**Windmill Lane, Ridgemill Drive, Windsor Road, Batley Field Hill, Grosvenor Road, York Road, Sunny Bank Road, Batley**

**Statement of reasons**

Complaints have been received stating that drivers associated with the schools on and facing Windmill Lane are parking on both sides of the road along its full length and around the junctions of Windsor Road and Ridgemill Drive. This is obstructing access along the road and blocking visibility for pupils travelling to and from school.

To resolve these problems, it is proposed to provide 'No Waiting at Any Time' restrictions at the junction of Windsor Road and Ridgeway Drive, as well as at strategic points on one side of Windmill Lane. This is intended to maintain access into and out of the school and provide a passing point for drivers to pull onto in order to wait to allow other vehicles to pass.

Site visits have also shown that parking takes place on both sides of Grosvenor Road, up and on the bend. Following a report of a number of damage only traffic collisions taking place at this location (the result of the parking taking place here), it is proposed to introduce sections of 'No Waiting At Any Time' parking restrictions at this location and around the junction with York Road and Sunny Bank Road, in order to improve access and visibility at these locations.

It is also proposed to provide waiting restrictions on Batley Field Hill on the north-east side of the junction of York Road to prevent parked vehicles from obstructing access and visibility for drivers exiting from the junction.

It is intended these proposals will help facilitate the free flow of traffic on the roads concerned and improve road safety for all road users.