Cannon Hall Contractors Document - Cawthorne Public Rights Of Way

WAITES
Tree
Surveys

Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
T085	Birch (Betula sp.)	Standing dead tree, next to path and rail line. Red dot. Sprayed with white dot	/// wealth.scar .boarding	Height (m): 10 Crown Radius (m): 0 DBH (cm): 30 Life Stage: Dead	Standing dead stem. Potential impact rail line.	Fell tree.	15-Oct-2024 (3 Months)
G016	Black pine (Pinus nigra) Hazel x2 (Corylus avellana)	Lapsed trees over path	/// bookings.th ings.value	DBH (cm): 50 Trees: 3 Life Stage: Mature Life Exp.: <10 years	Trees failed at root plate onto path, making path unpassable.	Remove trees to ensure path clearance.	15-Jan-2025 (6 Months)
T088	Pedunculate oak (Quercus robur)	On path running north from PROW along field edge	/// songbird.se ttled.cargo	Height (m): 19 Crown Radius (m): 6 DBH (cm): 70 Life Stage: Mature Life Exp.: 30+ Years	Tall form, directly next to path. Recent snap out of main limb currently lying over path and next to path. Secondary limb also failed and on the floor leaving approximately 50% of the canopy remaining. Historic wound at base of main stem leaving to small cavity sealing well most up	Clean up fallen branches from path	15-Jan-2025 (6 Months)
G015	Black pine x4 (Pinus nigra)	Group either side of auxillary path, potential to impact PROW. All Marked with White Dot	/// website.po ses.taxpaye rs	Height (m): 20 Crown Radius (m): 3 DBH (cm): 50 Trees: 4 Life Stage: Early Mature Life Exp.: <10 years	Group of trees all windblown, resting on line of trees next to PROW	Fell trees	02-Jul-2025 (1 Year)

Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
T076	Black pine (Pinus nigra)	W of PROW. Near woodland path entrance. Marked with White Dot	/// swimsuits.someone.wiping	Height (m): 20 Crown Radius (m): 2 DBH (cm): 30 Life Stage: Mature Life Exp.: <10 years	Failed on root plate. Leaning on neighbouring trees towards path	Fell tree.	02-Jul-2025 (1 Year)
T077	Pedunculate oak (Quercus robur)	Next to PROW near gated golf course entrance	/// pitch.landlady.tested	Height (m): 18 Crown Radius (m): 5 DBH (cm): 40 Life Stage: Mature Life Exp.: 50+ Years	Strong buttress roots. Fairly broad form. Two snapped branches hanging up reaching ground but still attached.	Remove snapped branches	02-Jul-2025 (1 Year)
							
T078	Sycamore (Acer pseudoplatanus)	NW of PROW.	/// spirits.condensed.untrained	Height (m): 14 Crown Radius (m): 7 DBH (cm): 50 Life Stage: Dead	Standing dead tree, canopy over PROW	Fell tree.	02-Jul-2025 (1 Year)
T079	Sycamore (Acer pseudoplatanus)	Directly next to path. Marked with White Dot	/// crust.sailor.partly	Height (m): 20 Crown Radius (m): 4 DBH (cm): 45 Stems: 2 Life Stage: Mature Life Exp.: <10 years	Severe bark damage, little circumference remaining. Tight main union with split down to butteress. Canopy weakening especially at tips.	Fell tree.	02-Jul-2025 (1 Year)
G017	Sycamore x3 (Acer pseudoplatanus)	Adam Lane, small group next to track.	/// notion.drilled.limits	Height (m): 16 Crown Radius (m): 6 DBH (cm): 55 Trees: 3 Life Stage: Mature Life Exp.: <10 years	Three mature trees dying back, all tips dead with some lower growth mainly epicormic. One tree has slight lean towards track, and another tree has moderate lean towards track. Two stems set back from Road.	Fell trees	15-Jul-2025 (1 Year)
T090	Wych elm (Ulmus glabra)	E of Waggon Way	/// promising.quantity.spelling	Height (m): 8 Crown Radius (m): 4 DBH (cm): 30 Stems: 4 Life Stage: Dead	Standing dead tree with slight lean towards path and some like over path. Ivy clad	Fell tree.	15-Jul-2025 (1 Year)

Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
G019	Sycamore x5 (Acer pseudoplatanus)	Small group at between perimeter and internal path, around opening with bramble undergrowth	/// micro.belong.nosedive	Height (m): 10 Crown Radius (m): 4 DBH (cm): 55 Trees: 5 Life Stage: Dead	Group of mainly dead stems all next to pathways. One stem failed leaving totem. One tree not completely dead but only foliage on lowest branches. In severe decline.	Fell trees or leave as 3m totems if possible	29-Jul-2025 (1 Year)
							
T100	Common ash (Fraxinus excelsior)	On woodland edge next to path and field. Under electricity cables	/// shame.terminal.fuses	Height (m): 6 Crown Radius (m): 3 DBH (cm): 45 Stems: 4 Life Stage: Semi Mature Life Exp.: 10+ Years	Small group of stems in bank side. Main stem with strong lean N towards path. Previously cut hard by utilities. Regrowth growing into lines, utilities issue	Fell tree.	29-Jul-2025 (1 Year)
T101	Pedunculate oak (Quercus robur)	Field side of wall next to PROW	/// accented.toasted.harp	Height (m): 14 Crown Radius (m): 6 DBH (cm): 60 Life Stage: Mature Life Exp.: 50+ Years	Tree in small group, canopy over path. Good form and vitality. One moderate snapped branch directly over path, slight obstruction.	Remove snapped branch	29-Jul-2025 (1 Year)
T105	Pedunculate oak (Quercus robur)	Next to path over stream crossing	/// tulip.craft.cuddled	Height (m): 17 Crown Radius (m): 4 DBH (cm): 55 Life Stage: Mature Life Exp.: 30+ Years	Growing out of bankside. Woodland style tree, no lower canopy. Large branch failed over path. Still attached at failure point.	Remove large hung up branch	29-Jul-2025 (1 Year)
							
T106	Silver birch (Betula pendula)	Next to path near woodland edge.	/// upstairs.vineyard.unhappily	Height (m): 9 DBH (cm): 40 Life Stage: Dead	Standing dead tree, lean away from path with canopy leaning towards the path	Fell tree.	29-Jul-2025 (1 Year)
T107	Pedunculate oak (Quercus robur)	E of path into woodland.	/// awakes.sulky.kilt	Height (m): 15 Crown Radius (m): 7 DBH (cm): 60 Stems: 2 Life Stage: Mature Life Exp.: 30+ Years	Dual stemmed tree, small stem still standing with slight lean towards path. Main stem failed at 6m, still attached, away from path, impacting neighbouring tree of high amenity value.	Remove snapped main stem leaving tear out section for wildlife	29-Jul-2025 (1 Year)
T108	Sycamore (Acer pseudoplatanus)	Directly next to path on slight bend. Sycamore and hazel shoots at base	/// wounds.active.flick	Height (m): 17 Crown Radius (m): 3 DBH (cm): 45 Life Stage: Dead	Large standing dead tree. Recent. Branches still attached. Large diameter lower limbs over path	Fell tree.	29-Jul-2025 (1 Year)

Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
T110	Scots pine (Pinus sylvestris)	Leaning over PROW	/// engulfing.delighted.lamppost	Height (m): 6 DBH (cm): 15 Life Stage: Young Life Exp.: <10 years	Failed at lower stem, resting in tree other side of path. Thin spindly growth pattern.	Fell tree.	29-Jul-2025 (1 Year)
T112	Pedunculate oak (Quercus robur)	Fallen tree over path	/// depth.chef.newer	DBH (cm): 50 Life Stage: Mature Life Exp.: <10 years	Tree failed at root plate. On the floor so currently safe, redirecting footpath over water ditch.	Remove section of stem to re-establish footpath	29-Jul-2025 (1 Year)
T114	Larch (Larix sp.)	Set back onto woodland from perimeter path	/// pipes.awoke.smooth	Height (m): 10 Crown Radius (m): 2 DBH (cm): 40 Life Stage: Mature Life Exp.: <10 years	Lapsed tree, hung up in neighbouring trees other side of path.	Fell tree.	29-Jul-2025 (1 Year)
T118	Spruce (Picea sp.)	Two trees set back from main PROW path	/// force.afterglow.learns	Height (m): 20 Crown Radius (m): 2.5 DBH (cm): 40 Stems: 2 Life Stage: Dead	Two standing dead trees in relatively close proximity to PROW. Bark peeling at main stem.	Fell trees	29-Jul-2025 (1 Year)
T119	Sweet chestnut (Castanea sativa)	Next to PROW, growing directly next to pine.	/// headlines.melon.regarding	Height (m): 17 Crown Radius (m): 5 DBH (cm): 50 Life Stage: Mature Life Exp.: 30+ Years	Large lower limb has failed. Touching floor but butt hanging in air propped on smaller branch.	Remove or make safe snapped out limb	29-Jul-2025 (1 Year)
T120	Silver birch (Betula pendula)	Next to path.	/// speeded.indicated.discouraged	Height (m): 12 Crown Radius (m): 2 DBH (cm): 40 Life Stage: Dead	Standing dead tree, sprayed with red dot. Slight lean perpendicular to path.	Fell tree.	29-Jul-2025 (1 Year)
T123	Pedunculate oak (Quercus robur)	Next to path. Slight lean away	/// snacking.signs.woods	Height (m): 11 Crown Radius (m): 3 DBH (cm): 65 Life Stage: Dead	Standing dead tree, canopy mainly decomposed but retaining scaffold limbs. Red dot sprayed on stem. Slight lean away from path.	Remove path side branches if deemed necessary by land manager. Retain for wildflife. Several cavities up main stem.	29-Jul-2025 (1 Year)
T124	Pedunculate oak (Quercus robur)	Directly next to path.	/// warm.spurring.branch	Height (m): 19 Crown Radius (m): 7 DBH (cm): 75 Life Stage: Mature Life Exp.: 50+ Years	Tall broad form. Canopy starts at 5m. Two larger failed branches, still attached, one hanging directly over path.	Removed attached dead branches.	29-Jul-2025 (1 Year)
T081	Goat willow (Salix caprea)	At far end of car park.	/// mass.celebrate.reservoir	Height (m): 16 Crown Radius (m): 2 DBH (cm): 25 Life Stage: Mature Life Exp.: <10 years	Wound at base, 2m high. Ivy clad main stem. Tree sealing but decay evident.	Fell tree.	15-Jul-2026 (2 Years)

Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
T082	Wych elm (Ulmus glabra)	w of track leading to scout camp	/// dwell.airbase.broker	Height (m): 15 Crown Radius (m): 2 DBH (cm): 40 Life Stage: Dead	Standing dead tree with slight lean over road	Fell tree.	15-Jul-2026 (2 Years)
T083	Black pine (Pinus nigra)	Set back in woodland in wedge between scout track and footpath.	/// juicy.ribcage.bank	Height (m): 22 Crown Radius (m): 2.5 DBH (cm): 55 Life Stage: Mature Life Exp.: 30+ Years	Tall woodland form. Multi stemmed at 12m. One stem has failed towards path and is leaning in neighbouring tree.	Remove failed main stem	15-Jul-2026 (2 Years)
T084	Goat willow (Salix caprea)	North of path next to railway	/// with.capillary.idea	Height (m): 5 Crown Radius (m): 3 DBH (cm): 20 Life Stage: Mature Life Exp.: <10 years	Tree failed at stem. Leaning towards path and railway, hung up in tree line edge. Not long enough to reach line.	Fell tree.	15-Jul-2026 (2 Years)
T086	Common ash (Fraxinus excelsior)	North of and directly next to PROW. Proximity to power cables.	/// sleepy.drift.liability	Height (m): 20 Crown Radius (m): 4 DBH (cm): 55 Stems: 2 Life Stage: Mature Life Exp.: <10 years	Hawthorn at base. Weakening canopies, foliage solely at the the top, tip die back throughout.	Fell tree.	15-Jul-2026 (2 Years)
T087	Sycamore (Acer pseudoplatanus)	Between footpath and field, North of disused railway.	/// snowballs.reminds.blurred	Height (m): 15 Crown Radius (m): 5 Life Stage: Dead	Standing dead tree set back from footpath, holly undergrowth	Fell tree.	15-Jul-2026 (2 Years)
T089	Sycamore (Acer pseudoplatanus)	SW of track in edge of woodlamd	/// sprinter.appetite.insulated	Height (m): 10 Crown Radius (m): 4 DBH (cm): 50 Life Stage: Dead	Standing dead tree. Ivy clad main stem. Potential to impact path in event of failure	Fell tree.	15-Jul-2026 (2 Years)
T093	Common beech (Fagus sylvatica)	Next to small path near gateway on track, Haddon Green	/// submitted.chopper.business	Height (m): 16 Crown Radius (m): 6 DBH (cm): 105 Life Stage: Mature Life Exp.: <10 years	Double Stemmed from 2m. In decline. Upper canopy dying back. Secondary stem has failed leaving totem. Fungal brackets in union. Dead patches of bark up main stem. Fungus: Ganoderma australe (Southern Bracket)	Fell tree.	15-Jul-2026 (2 Years)

Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
T094	Sycamore (Acer pseudoplatanus)	N of track.	///sending.townhouse.apprehend	Height (m): 11 Crown Radius (m): 2.5 DBH (cm): 25 Life Stage: Dead	Standing dead tree, holly undergrowth	Fell tree.	15-Jul-2026 (2 Years)
T095	Wych elm (Ulmus glabra)	N of track near road entrance	///exchanges.steeped.cassettes	Height (m): 12 Crown Radius (m): 3 DBH (cm): 35 Life Stage: Dead	Standing dead tree, still mainly intact	Fell tree.	15-Jul-2026 (2 Years)
T096	Sycamore (Acer pseudoplatanus)	On path edge, next to wall	///trap.drops.appointed	Height (m): 9 Crown Radius (m): 4 DBH (cm): 20 Stems: 2 Life Stage: Semi Mature Life Exp.: 30+ Years	Dual stemmed tree, stem leaning towards field appears healthy. Path side stem completely dead, slight lean into path and dead branches over path.	Remove dead stem to ground level	15-Jul-2026 (2 Years)
T097	Sycamore (Acer pseudoplatanus)	N of path on section to smaller weak sycamore	///newsprint.shelf.flap	Height (m): 11 Crown Radius (m): 5 DBH (cm): 50 Life Stage: Mature Life Exp.: <10 years	Growing in hedgerow. Canopy dying back, especially one field side limb. Only foliage is upper canopy and fairly sparse. In decline	Fell tree and remove small dead stems from hedgerow either side	15-Jul-2026 (2 Years)
G018	Mixed species x4 (Mixed species)	Lapsed trees across path	///cigar.gobblers.tanks	DBH (cm): 40 Trees: 4 Life Stage: Dead	Failed trees in section of path. Lying on ground, block access.	Remove timber section blocking path	29-Jul-2026 (2 Years)
G020	Wych elm x6 (Ulmus glabra)	Next to path leading to Woodland	///articulated.thrones.rainwater	Height (m): 9 Trees: 6 Life Stage: Dead	Multiple dead stems with smaller dead stems at base.	Fell trees	29-Jul-2026 (2 Years)
T098	Common ash (Fraxinus excelsior)	At entrance to path leading Cricket ground	///unloads.wanting.general	Height (m): 14 Crown Radius (m): 4 DBH (cm): 35 Life Stage: Semi Mature Life Exp.: <10 years	Ivy clad stem, severed. Severe ADB symptoms, with minimal foliage remaining, due to decline Pests and Diseases: Ash Dieback Infection Level 3: 50% to 75%	Fell tree.	29-Jul-2026 (2 Years)
T099	Wych elm (Ulmus glabra)	Next to small bridge. Ownership uncertain	///pencil.concerts.houseboat	Height (m): 15 Crown Radius (m): 3 DBH (cm): 25 Stems: 3 Life Stage: Dead	Standing dead tree, on bank side.	Fell tree.	29-Jul-2026 (2 Years)
T102	Common ash (Fraxinus excelsior)	Field side tree next to path, growing next to wall	///remembers.bands.insect	Height (m): 20 Crown Radius (m): 7 DBH (cm): 75 Life Stage: Mature Life Exp.: 10+ Years	Large reactionary butteress, with cavity at base leading to substantial white rot. Small fungal bracket at soil level. Canopy vitality is good with little further stress growth.	Monitor spread of fungal brackets and decay in centre	FOR SURVEYOR NOT CONTRACTOR 29-Jul-2026 (2 Years)



Ref.	Species	Description	What 3 Words	Measurements	Survey Notes	Recommendation	Work Timescale
T103	Common ash (Fraxinus excelsior)	Next to boundary wall, N of small auxiliary path	/// corrode.abacus.tonal	Height (m): 11 Crown Radius (m): 2.5 DBH (cm): 65 Life Stage: Mature Life Exp.: 10+ Years	Top has failed. Resting in neighbouring tree directly next to path. Epicormic response making new canopy.	Remove hung up snapped out top.	29-Jul-2026 (2 Years)
T104	Sycamore (Acer pseudoplatanus)	Directly next to path near path split.	/// confirms.justifies.mermaids	Height (m): 13 Crown Radius (m): 1 DBH (cm): 30 Life Stage: Semi Mature Life Exp.: <10 years	Wounds all up main stem. Dead top with foliage only lower epicormic.	Fell tree.	29-Jul-2026 (2 Years)
T109	Scots pine (Pinus sylvestris)	At junction of PROW and path.	/// shuttling.voltages.mergers	Height (m): 14 Crown Radius (m): 1 DBH (cm): 20 Life Stage: Dead	Standing dead tree, slightly set back from path. Potential to impact both path and PROW.	Fell tree.	29-Jul-2026 (2 Years)
T111	Scots pine (Pinus sylvestris)	Next to path, leaning over path	/// pace.bolsters.caged	Height (m): 14 Crown Radius (m): 4 DBH (cm): 40 Life Stage: Mature Life Exp.: 30+ Years	Butteress roots, slight lean over path. Two major branches failed and hanging directly over path, still attached at failure points. S	Remove and hung up branches	29-Jul-2026 (2 Years)
T113	Common beech (Fagus sylvatica)	Standing dead tree slightly set back from path	/// president.padding.snipe	Height (m): 17 Crown Radius (m): 5 DBH (cm): 50 Life Stage: Dead	Large standing dead tree, with smaller live stem growing next to it. Upright form, with some larger dead limbsleanig towards the path.	Fell tree.	29-Jul-2026 (2 Years)
T115	Larch (Larix sp.)	Lapsed tree leanig over path	/// suggested.mattress.fired	Height (m): 16 Crown Radius (m): 3 DBH (cm): 40 Life Stage: Mature Life Exp.: <10 years	Failed at root plate. Leaning against tree opposite side of path. Still live. Potential to fail and block path	Fell tree.	29-Jul-2026 (2 Years)
T121	Pine (Pinus sp.)	Dead lapsed tree over path.	/// vowel.since.scoop	DBH (cm): 35 Life Stage: Dead	Failed at stem. Leaning over path and resting on canopy of yew other side of path. Growth up stem shows has been in place a while. Potential to fail and block path	Fell tree and remove from Yew canopy.	29-Jul-2026 (2 Years)
T122	Rowan (Sorbus aucuparia)	Failed stems on path at woodland entrance.	/// chestnuts.chimp.friction	DBH (cm): 15 Life Stage: Dead	Failed stems. Blocking path next to info sign.	Clear up stems in path if deemed necessary	29-Jul-2026 (2 Years)
T126	Scots pine (Pinus sylvestris)	Next to footpath, sprayed with red dot.	/// ditched.quoted.receiving	Height (m): 16 Crown Radius (m): 3 DBH (cm): 35 Life Stage: Mature Life Exp.: <10 years	Lapsed at root plate. Still standing but with moderate to severe lean, over footpath.	Fell tree.	29-Jul-2026 (2 Years)
T127	Silver birch (Betula pendula)	Directly next to path	/// hairspray.hood.collect	Height (m): 15 Crown Radius (m): 4 DBH (cm): 45 Life Stage: Dead	Standing dead tree. Upright form. Recent death, branches still intact, some over footpath	Fell tree.	29-Jul-2026 (2 Years)