




PLAN OF BOX CULVERT BASE

UNDERSIDE OF BOX CULVERTS TO CONSIST OF:
50mm CLASS 6L MATERIAL DN, 150mm CLASS 6K MATERIAL.
FORMATION LEVEL TO BE PROOF ROLLED AND INSPECTED BY ENGINEER FROM HHA & ERDYC AND ADDITIONAL 6F2 TO BE USED IF REQUIRED.




PLAN OF BOX CULVERT ROOF SLAB

UNDERSIDE OF BOX CULVERTS TO CONSIST OF:
50mm CLASS 6L MATERIAL DN, 150mm CLASS 6K MATERIAL.
FORMATION LEVEL TO BE PROOF ROLLED AND INSPECTED BY ENGINEER FROM HHA & ERDYC AND ADDITIONAL 6F2 TO BE USED IF REQUIRED.




DETAIL 1 SCALE 1:5



ADEQUATE BEARING STRATA TO BE CONFIRMED IN WRITING TO KIRKLEES.
IF AN ALLOWABLE BEARING PRESSURE OF 60kN/m² CANNOT BE CONFIRMED, A FURTHER DEPTH OF MATERIAL SHALL BE EXCAVATED ALL ARDUND THE CONCRETE BASE AND REPLACED WITH MASS CONCRETE.

TYPICAL SECTION SHOWING WING WALL CONSTRUCTION DETAILS



CULVERT LOCATION PLAN
SCALE 1:200

Haigh Huddleston & Associates
Civil Structural Engineering Consultants
Firth Buildings, 99 - 101 Leeds Rd, Dewsbury, WF12 7BU t 01924 464342 f 01924 450662
e trevor.haigh@haighhuddleston.co.uk

Client
YORKSHIRE COUNTRY PROPERTIES

Project
GYNN LANE, HONLEY

Detail
ROAD 1 CULVERT/HEADWALL CONSTRUCTION DETAILS (DRAWING 1OF2)

PRELIMINARY

Dwn	Chkd	Date	Scale	Dwg No.
PW	MH	Mar 24	1:50 1:250	E24/8017/200_01A

Rev A Overflow pipe added 16.01.26PW