



KEY

CP 13 Amp SOCKET TO ALL PLOTS WHERE A PRACTICAL POSITION CAN BE PROVIDED

PLOTS WITHOUT CHARGING POINTS ARE 46,50,60,61

