

Shepley Phase 2 - House plot amendments

Plot number	Previous house type	New house type
32	U	U
33	C2	C
34	C2	C
35	U	U
36	A1	B1
37	A1	B1
38	A1	B1
39	A1	B1
40	A1	D1
41	A1	D1
42	A1	B2
43	A1	B2
44	A1	C
45	A1	C
46	D	R
47	C	B2
48	C	B2
49	D	U
50	B	U
51	B	R1
52	U	Y
53	BU	C
54	D	C
55	C	C
56	C	C
57	D	D2
58	N	B2
59	P	B2
60	D2	C1
61	D	C1
62	D1	L2
63	D1	L2
64	D	C
65	N	C
66	P	C1
67	T	C1
68	S	C1
69	T	C1
70	S	C
71	L1	C
72	W	W (semi)
73	W (semi)	W (semi)
74	W (semi)	W (semi)
75	W (semi)	W (semi)
76	W (semi)	W (semi)
77	W (semi)	W (semi)
78	W (semi)	W (semi)
79	D	D

80	D1	D1
81	L1	L2
82	V (semi)	V (semi)
83	V (semi)	V (semi)

Shepley Phase 2 - House type amendments

Existing house type	Material amendments
C	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Fixed side light to entrance door removed
	Glazed window within entrance door amended
	Dental course removed
	Bi-fold doors amended to double doors with fixed side lights
D	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Dental course removed
	Watertables removed
D1	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Glazed window within entrance door amended
	Stone surround to entrance door amended
	Dental course removed
	Footprint of house extended with a single storey extension to rear
D2	Single storey side extension removed
	Entrance porch removed
	Bay window added
	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Fixed side light added to entrance door
	Dental course removed
L2	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Watertables removed
	Door added to utility room
	Height of building reduced
	Small windows within entrance lobby removed
W (semi)	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Dental course removed
V	Stone window jambs and central stone mullion removed
	Central horizontal mullion added to windows
	Dental course removed
	Arch lintel above garage amended
	Flat roof above bay window changed to pitched roof
	Watertables removed
	Glazed window within entrance door amended