

LEGEND

Manhole shown thus  
Inspection Cover  
Lamp Post  
Gully  
Lamp Post  
Telegraph Post  
Electricity Poles  
Road Traffic Signs  
Traffic Lights  
General Post Office  
Post Office Telephones  
Fire Hydrant  
Safety Valve  
Stopcock Water  
Stopcock Gas  
Unknown Stopcock

MH  
IC  
LH  
G  
EP  
TP  
EP  
RS  
TL  
GPO  
POT  
FH  
SV  
SCW  
Gas  
ST

Spot Level  
Kerb Line  
Fence Line  
Hedge Line  
Contours 5m interval  
Contours 1m interval  
Tree Spread  
S.O.  
Girth  
Cover Level  
Invert Level  
Foul Drain  
Surface Water  
Unknown Service  
Survey Station

+123.562  
Height floor to structural soffit  
Height floor to false ceiling  
Height floor to sill  
Height of window  
Height of door  
Height floor to underside of beam  
US 3.61  
S.O.  
Girth  
CL 112.335  
L 111.733  
Vent  
Fall Pipe  
Sky Light  
Water Closet  
Sink  
Bored Column  
Shop fitting or cladding

FL 10.907  
SS 2.87  
FC 2.22  
S.O.67  
W 1.23  
D 1.98  
US 3.61  
V  
FP  
SL  
WC  
S  
L

SITE SURVEY

THONGSBRIDGE CRICKET CLUB,  
MIRY LANE, THONGSBRIDGE,  
HOLMFIRTH.

Sheet Diagram

Datum

GRN- Related to  
Ordnance Survey using  
One Point Localisation on  
Station S1. Orientation at  
OS Grid North.

LEVEL- Related to  
Ordnance Survey by  
connection to the OS  
Active Network by G.P.S

Sheet 1 of 1

Surveyed by SH

Drawn by SH

Checked by PBT

Survey Job No. S7316

Date of Survey

August 2010

Scale 1/200

**S7316**

414920E

414880E

414860E

414920E

414880E

414860E

414960E

414960E

409840N

409800N

409760N

409720N