


SEVERITY		District		Kirklees		Brockholes Site Frontage - 01/08/2010 to 31/07/2015		Grid Reference		414686 / 410977											
SLIGHT		Ref.No		130313173		Road		A6024		Location		Woodhead Road, Holmfirth, Kirklees.									
Date		26/07/2013		Day		Friday		Description		V1 Travels Along Woodhead Road Towards Holmfirth. V2 Has Overtaken V1 and Pulled up Further down Carriageway. Rider of V2 Gets off Vehicle and Attempts to Flag down V1 to Speak to Driver. it is Alleged V1 Swerves Intentionally Towards Rider of V2 Clipping Him with Os Wing Mirror.		Police Officer Attend:		No - reported over the counter							
Time		16:46		Weather		Fine without high winds		Road Surface		Dry		Street Lighting		Daylight							
Speed Limit		40 MPH		Carrivageway		Single carriageway		Junction Detail		Not at or within 20 metres of junction		Junction Control									
2nd Road Number				Pedestrian Facilities		None within 50 metres		No physical crossing facility within 50 m				CONTRIBUTORY FACTORS		PARTICIPANT PROBABILITY							
VEHICLES INVOLVED		2										CASUALTIES INVOLVED		1							
Veh.No. 1		Vehicle type		Car		Make		Model		Cas No		1		Cas Class		Driver or Rider		Veh ref No		2	
Manoeuvre		Going ahead other		Towing?		No tow or articulation				Severity		SLIGHT		Age		42 yrs		Sex		Male	
Veh. direction from		Northwest to Southeast		Skidded		No skidding, jack-knifing or overturning		Veh location at impact (restricted lane)		On main carriageway not in restricted lane		Car Passenger?		Not a passenger		Seat Belt		Not applicable		PSV Passenger? Not a passenger	
Junct. location of veh. at 1st impact		Not at or within 20m of junction		Veh left carriageway?		Did not leave carriageway		Hit object in c'way?		None		Ped Movement		Not applicable		Ped Location		Not applicable		Cycle Helmet	
Hit object off c'way?		None		First point of impact		Offside		Veh registration no.		Other veh.hit (ref.no)		0		Hit and run		Not hit and run					
Drivers age		22 yrs		Sex		Male		Breath test		Driver not contacted		Driving Lic									
Left Hand Drive		Unknown		Journey purpose		Other		Foreign veh.		Not foreign registered vehicle											
Veh.No. 2		Vehicle type		M/cycle > 500cc		Make		Model		Other Details											
Manoeuvre		Parked		Towing?		No tow or articulation															
Veh. direction from		Parked to Parked		Skidded		No skidding, jack-knifing or overturning		Veh location at impact (restricted lane)		On main carriageway not in restricted lane											
Junct. location of veh. at 1st impact		Not at or within 20m of junction		Veh left carriageway?		Did not leave carriageway		Hit object in c'way?		None											
Hit object off c'way?		None		First point of impact		Did not impact		Veh registration no.		Other veh.hit (ref.no)		0		Hit and run		Not hit and run					
Drivers age		42 yrs		Sex		Male		Breath test		Driver not contacted		Driving Lic									
Left Hand Drive		Unknown		Journey purpose		Other		Foreign veh.		Not foreign registered vehicle											



© Crown Copyright and database right 2015
Ordnance Survey 100019241



Streetscene & Housing
Flint Street, Fartown
Huddersfield, HD1 6LG

20010492 Brockholes
Junctions 1,2,3

Accident data
01-08-2010 to 31-07-2015

Scale

NTS

Drawn
PW

Checked

Section
SAFETY

Date
AUG 15

Drawing No.

SEVERITY		District Kirklees		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414088 / 412010	
SLIGHT		Ref.No 10EA0551663		Road A6024 Location Woodhead Road Jw Station Road, Honley, Holmfirth		Police Officer Attend: Yes	
Date	28/12/2010	Day	Tuesday	Description V1 Travelling Along Woodhead Road Towards Huddersfield. V2 Travelling Along Station Road Towards Junction with Woodhead Road.			
Time	16:40	of Accident V1 & V2 Pass Through Traffic Lights at the Same Time & Collide in the Middle.					
Weather	Fine without high winds						
Road Surface	Wet/Damp						
Street Lighting	Dark: street lights present and lit						
SITE DETAILS				CONTRIBUTORY FACTORS		PARTICIPANT PROBABILITY	
Speed Limit	30 MPH	SPECIAL SITE CONDITIONS		405 Failed to look properly (Driver/Rider - Error)		Vehicle 001 B	
Carriageway	Single carriageway	None					
Junction Detail	Crossroads	CARRIAGEWAY HAZARDS					
Junction Control	Automatic traffic signal	None					
2nd Road Number	U						
Pedestrian Facilities	None within 50 metres						
	No physical crossing facility within 50 m						
VEHICLES INVOLVED 2							
Veh.No. 1	Vehicle type Car	Make	Model	CASUALTIES INVOLVED 1			
Manoeuvre	Going ahead other			Cas No	1	Cas Class	Driver or Rider
Veh. direction from	South to North	Towing?	No tow or articulation	Severity	SLIGHT	Age	29 yrs
Skidded	No skidding, jack-knifing or overturning			Car Passenger?	Not a passenger	Sex	Male
Veh location at impact (restricted lane)	On main carriageway not in restricted lane			Seat Belt	Not applicable	PSV Passenger?	Not a passenger
Junct. location of veh. at 1st impact	Cleared junction or waiting			Ped Movement	Not applicable	Cycle Helmet	
Veh left carriageway?	Did not leave carriageway			Ped Location	Not applicable		
Hit object in c'way?	None			Ped Direction to	Not applicable		
Hit object off c'way?	None			School Pupil	Other		
First point of impact	Front			Roadworker injured			
Veh registration no.		Other veh.hit (ref.no)	2	<u>Other Details</u>			
Drivers age	67 yrs	Breath test	Negative				
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						
Veh.No. 2	Vehicle type Car	Make	Model				
Manoeuvre	Going ahead other						
Veh. direction from	East to West	Towing?	No tow or articulation				
Skidded	No skidding, jack-knifing or overturning						
Veh location at impact (restricted lane)	On main carriageway not in restricted lane						
Junct. location of veh. at 1st impact	Cleared junction or waiting						
Veh left carriageway?	Did not leave carriageway						
Hit object in c'way?	None						
Hit object off c'way?	None						
First point of impact	Nearside						
Veh registration no.		Other veh.hit (ref.no)	1				
Drivers age	29 yrs	Breath test	Not requested				
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						

SEVERITY		District Kirklees		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414218 / 411976	
SLIGHT		Ref.No 110025563		Road A616 Location New Mill Road, in Vicinity of Station Road, Honley		Police Officer Attend: No - reported over the counter	
Date	17/01/2011	Day	Monday	Description Veh 1 was on New Mill Road Travelling Towards Honley Had Stopped to Overtake a Parked Vehicle Parked Outside Property was of Accident Indicating to Go Round It. Veh 2 was Travelling Behind Veh 1 Failed to Notice That Veh 1 Had Stopped and Collides into the Rear of It.			
Time	16:40						
Weather	Other						
Road Surface	Dry						
Street Lighting	Dark: street lights present and lit						
SITE DETAILS		SPECIAL SITE CONDITIONS		CONTRIBUTORY FACTORS		PARTICIPANT PROBABILITY	
Speed Limit	30 MPH	None		405 Failed to look properly (Driver/Rider - Error)		Vehicle 002 B	
Carriageway	Single carriageway	CARRIAGEWAY HAZARDS		701 Stationary or parked vehicle(s) (Driver/Rider - Vision Affe		Vehicle 001 A	
Junction Detail	Not at or within 20 metres of junction	None					
Junction Control							
2nd Road Number							
Pedestrian Facilities	None within 50 metres						
	No physical crossing facility within 50 m						
VEHICLES INVOLVED 2							
Veh.No. 1	Vehicle type Car	Make	Model	CASUALTIES INVOLVED 1			
Manoeuvre	Waiting to go ahead but held up			Cas No	1	Cas Class	Driver or Rider
Veh. direction from	North to North	Towing?	No tow or articulation	Severity	SLIGHT	Age	26 yrs
Skidded	No skidding, jack-knifing or overturning			Car Passenger?	Not a passenger	Sex	Male
Veh location at impact (restricted lane)	On main carriageway not in restricted lane			Seat Belt	Not applicable	PSV Passenger?	Not a passenger
Junct. location of veh. at 1st impact	Not at or within 20m of junction			Ped Movement	Not applicable	Cycle Helmet	
Veh left carriageway?	Did not leave carriageway			Ped Location	Not applicable		
Hit object in c'way?	None			Ped Direction to	Not applicable		
Hit object off c'way?	None			School Pupil	Other		
First point of impact	Back			Roadworker injured			
Veh registration no.	Other veh.hit (ref.no) 2			<u>Other Details</u>			
Drivers age	26 yrs	Sex	Male				
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Commuting to/from work						
Veh.No. 2	Vehicle type Car	Make	Model				
Manoeuvre	Going ahead other						
Veh. direction from	North to North	Towing?	No tow or articulation				
Skidded	No skidding, jack-knifing or overturning						
Veh location at impact (restricted lane)	On main carriageway not in restricted lane						
Junct. location of veh. at 1st impact	Not at or within 20m of junction						
Veh left carriageway?	Did not leave carriageway						
Hit object in c'way?	None						
Hit object off c'way?	None						
First point of impact	Front						
Veh registration no.	Other veh.hit (ref.no) 1						
Drivers age	? yrs	Sex	Not know				
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						

SEVERITY		District Kirklees		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414087 / 412012	
SLIGHT		Ref.No 110028123		Road A6024 Location Woodhead Road Jw Northgate, Huddersfield		Police Officer Attend: Yes	
Date	19/01/2011	Day	Wednesday	Description V1 Pedal Cycle Travelling Along Woodhead Rd from Holmfirth in the Direction of Huddersfield. V2 Car is Travelling from Northgate of Accident Towards Station Road Crossing Woodhead Rd. V1 Approach Red Traffic Lights and Continues Through, V2 Stationary at Red Traffic Light. Lights Change to Green and V2 Sets Off. a Collision Occurs in Centre of Junction.			
Time	08:12	Weather Fine without high winds					
Road Surface	Dry	Street Lighting Daylight					
SPECIAL SITE CONDITIONS				CONTRIBUTORY FACTORS			
Speed Limit	30 MPH	SPECIAL SITE CONDITIONS		405 Failed to look properly (Driver/Rider - Error)			
Carrivageway	Single carrivageway	None		PARTICIPANT PROBABILITY			
Junction Detail	Crossroads	CARRIAGEWAY HAZARDS		Vehicle 001 A			
Junction Control	Automatic traffic signal	None					
2nd Road Number	U						
Pedestrian Facilities	None within 50 metres						
	No physical crossing facility within 50 m						
VEHICLES INVOLVED 2							
Veh.No. 1	Vehicle type Pedal Cycle	Make	Model	CASUALTIES INVOLVED 1			
Manoeuvre	Going ahead other			Cas No	1	Cas Class	Driver or Rider
Veh. direction from	South to North	Towing?	No tow or articulation	Severity	SLIGHT	Age	17 yrs
Skidded	No skidding, jack-knifing or overturning			Car Passenger?	Not a passenger	Sex	Male
Veh location at impact (restricted lane)	On main carrivageway not in restricted lane			Seat Belt	Not applicable	PSV Passenger?	Not a passenger
Junct. location of veh. at 1st impact	Mid junction - on roundabout or main road			Ped Movement	Not applicable	Cycle Helmet	
Veh left carrivageway?	Did not leave carrivageway			Ped Location	Not applicable		
Hit object in c'way?	None			Ped Direction to	Not applicable		
Hit object off c'way?	None			School Pupil	Other		
First point of impact	Front			Roadworker injured			
Veh registration no.	Other veh.hit (ref.no) 2		Hit and run	<u>Other Details</u>			
Drivers age	17 yrs	Sex	Male	Breath test	Not Applicable	Driving Lic	
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						
Veh.No. 2	Vehicle type Car	Make	Model				
Manoeuvre	Going ahead other						
Veh. direction from	West to East	Towing?	No tow or articulation				
Skidded	No skidding, jack-knifing or overturning						
Veh location at impact (restricted lane)	On main carrivageway not in restricted lane						
Junct. location of veh. at 1st impact	Mid junction - on roundabout or main road						
Veh left carrivageway?	Did not leave carrivageway						
Hit object in c'way?	None						
Hit object off c'way?	None						
First point of impact	Offside						
Veh registration no.	Other veh.hit (ref.no) 1		Hit and run				
Drivers age	30 yrs	Sex	Female	Breath test	Negative	Driving Lic	
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						

SEVERITY SLIGHT		District Kirklees Ref.No 110031190		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414174 / 412017 Police Officer Attend: Yes	
Date 20/01/2011 Time 16:09	Day Thursday	Road A616	Location New Mill Road Jw Station Road, Holmfirth				
Weather Fine without high winds	Road Surface Dry	Description V1 is Travelling Along New Mill Road Towards Huddersfield & Turns right to Station Road and across the Path of V2 Travelling in the Opposite Direction. V1 then Collides with a Boundary Fence. V2 Collides with F/O/S of V3 which was Stationary at the Jct from Station Road.					
Street Lighting Daylight	SPECIAL SITE CONDITIONS None		CONTRIBUTORY FACTORS 405 Failed to look properly (Driver/Rider - Error) 406 Failed to judge other person's path/speed (Driver/Rider - E Vehicle 001 - B		PARTICIPANT PROBABILITY Vehicle 001 - A		
Speed Limit 30 MPH	CARRIAGEWAY HAZARDS None		VEHICLES INVOLVED 3				
Carrivageway Single carriageway	None		VEH.No. 1 Vehicle type Car Manoeuvre Turning right Veh. direction from Southeast to Northeast Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Leaving main road Veh left carriageway? Left carriageway nearside and rebounded Hit object in c'way? None Hit object off c'way? Other permanent object First point of impact Front Veh registration no. Other veh.hit (ref.no) 2 Hit and run Not hit and run Drivers age 19 yrs Sex Female Breath test Negative Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Commuting to/from work				
Junction Detail Crossroads	None		VEH.No. 2 Vehicle type Car Manoeuvre Waiting to go ahead but held up Veh. direction from Northwest to Southeast Towing? No tow or articulation Skidded Skidded Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Approaching junction or waiting Veh left carriageway? Did not leave carriageway Hit object in c'way? None Hit object off c'way? None First point of impact Front Veh registration no. Other veh.hit (ref.no) 3 Hit and run Not hit and run Drivers age 39 yrs Sex Male Breath test Negative Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Commuting to/from work				
Junction Control Give way or uncontrolled	None		CASUALTIES INVOLVED 2				
2nd Road Number U	None		Cas No 1 Cas Class Driver or Rider Veh ref No 1 Severity SLIGHT Age 19 yrs Sex Female Post code Car Passenger? Not a passenger PSV Passenger? Not a passenger Seat Belt Not applicable Cycle Helmet Ped Movement Not applicable Ped Location Not applicable Ped Direction to Not applicable School Pupil Other Roadworker injured				
Pedestrian Facilities None within 50 metres	None		Cas No 2 Cas Class Driver or Rider Veh ref No 2 Severity SLIGHT Age 39 yrs Sex Male Post code Car Passenger? Not a passenger PSV Passenger? Not a passenger Seat Belt Not applicable Cycle Helmet Ped Movement Not applicable Ped Location Not applicable Ped Direction to Not applicable School Pupil Other Roadworker injured				
No physical crossing facility within 50 m	None		Other Details				

Veh.No.	3	Vehicle type	Car	Make	Model
Manoeuvre	Parked				
Veh. direction from	Parked to Parked	Towing?	No tow or articulation		
Skidded	No skidding, jack-knifing or overturning				
Veh location at impact (restricted lane)	On main carriageway not in restricted lane				
Junct. location of veh. at 1st impact	Approaching junction or waiting				
Veh left carriageway?	Did not leave carriageway				
Hit object in c'way?	None				
Hit object off c'way?	None				
First point of impact	Front				
Veh registration no.		Other veh.hit (ref.no)	2	Hit and run	Not hit and run
Drivers age	45 yrs	Breath test	Driver not contacted	Driving Lic	
Sex	Female	Foreign veh.	Not foreign registered vehicle		
Left Hand Drive	Unknown				
Journey purpose	Commuting to/from work				

SEVERITY SLIGHT		District Kirklees Ref.No 110152879		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414090 / 412012 Police Officer Attend: No - reported over the counter	
Date	31/03/2011	Day	Thursday	Road	A6024	Location	Woodhead Road Jw Northgate, Honley, Holmfirth
Time	16:10	Weather	Fine with high winds	Description	V1 was Travelling on Northgate, Honley, V2 on Woodhead Road Towards Holmfirth. V2 Went Through a Red Light and Collided with of Accident V1 Hitting the Offside Front Wing Colliding Damage and Injuring the Driver and Passenger Who was Sat in the Rear of the Vehicle.		
Road Surface	Dry	Street Lighting	Daylight				
SITE DETAILS Speed Limit 30 MPH Carriageway Single carriageway Junction Detail Crossroads Junction Control Automatic traffic signal 2nd Road Number U Pedestrian Facilities Control by other authorised person Pedestrian phase at traffic signal junction				SPECIAL SITE CONDITIONS None CARRIAGEWAY HAZARDS None		CONTRIBUTORY FACTORS PARTICIPANT PROBABILITY	
VEHICLES INVOLVED 2				CASUALTIES INVOLVED 2			
Veh.No. 1 Vehicle type Car Manoeuvre Going ahead other Veh. direction from East to West Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Mid junction - on roundabout or main road Veh left carriageway? Did not leave carriageway Hit object in c'way? None Hit object off c'way? None First point of impact Offside Veh registration no. Other veh.hit (ref.no) 2 Hit and run Not hit and run Drivers age 37 yrs Sex Female Driver not contacted Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Taking pupil to/from school				Make Model Make Model Make Model			
Veh.No. 2 Vehicle type Car Manoeuvre Going ahead other Veh. direction from North to South Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Mid junction - on roundabout or main road Veh left carriageway? Did not leave carriageway Hit object in c'way? None Hit object off c'way? None First point of impact Front Veh registration no. Other veh.hit (ref.no) 1 Hit and run Not hit and run Drivers age ? yrs Sex Not know Driver not contacted Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Other				Make Model Make Model Make Model			
Other Details Other Details				Other Details Other Details			
Full Details				28-August-2015			
				Accident Ref.No 110152879			

SEVERITY		District Kirklees		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414161 / 412033	
SLIGHT		Ref.No 110165254		Road A616 Location New Mill Road Jw Station Road, Honley		Police Officer Attend: No - reported over the counter	
Date	08/04/2011	Day	Friday	Description V1 turning right from Station Road (Person Cannot Name Road she was turning Into). V2 Turned right from Offside of V1, from Opposite of Accident Direction at Same Time. as V2 Turns Allegedly at Speed, its Rear End Swung out and Caught the Front Nearside Bumper of V1. Exact Location Not Known. Probably New Mill Road.			
Time	15:45	Road A616 Location New Mill Road Jw Station Road, Honley					
Weather	Fine without high winds	CONTRIBUTORY FACTORS					
Road Surface	Dry	PARTICIPANT PROBABILITY					
Street Lighting	Daylight	Other Details					
Speed Limit	30 MPH	SPECIAL SITE CONDITIONS		CASUALTIES INVOLVED 1			
Carriageway	Single carriageway	None		Cas No	1	Cas Class	Driver or Rider
Junction Detail	Crossroads	CARRIAGEWAY HAZARDS		Severity	SLIGHT	Age	23 yrs
Junction Control	Give way or uncontrolled	None		Car Passenger?	Not a passenger	Sex	Female
2nd Road Number	U	Other Details					
Pedestrian Facilities	None within 50 metres	PSV Passenger? Not a passenger					
	No physical crossing facility within 50 m	Cycle Helmet					
		Not applicable					
		Not applicable					
		Not applicable					
		Not applicable					
		Other					
		Roadworker injured					
		Other Details					
VEHICLES INVOLVED 2							
Veh.No. 1	Vehicle type Car	Make	Model	Cas No	1	Cas Class	Driver or Rider
Manoeuvre	Going ahead other			Severity	SLIGHT	Age	23 yrs
Veh. direction from	North to North	Towing?	No tow or articulation	Car Passenger?	Not a passenger	Sex	Female
Skidded	No skidding, jack-knifing or overturning			Seat Belt	Not applicable	PSV Passenger?	Not a passenger
Veh location at impact (restricted lane)	On main carriageway not in restricted lane			Ped Movement	Not applicable	Cycle Helmet	
Junct. location of veh. at 1st impact	Mid junction - on roundabout or main road			Ped Location	Not applicable		
Veh left carriageway?	Did not leave carriageway			Ped Direction to	Not applicable		
Hit object in c'way?	None			School Pupil	Other		
Hit object off c'way?	None			Roadworker injured			
First point of impact	Front			Other Details			
Veh registration no.		Other veh.hit (ref.no)	2	Hit and run	Not hit and run		
Drivers age	23 yrs	Breath test	Driver not contacted	Driving Lic			
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						
Veh.No. 2	Vehicle type Car	Make	Model				
Manoeuvre	Going ahead other						
Veh. direction from	North to North	Towing?	No tow or articulation				
Skidded	No skidding, jack-knifing or overturning						
Veh location at impact (restricted lane)	On main carriageway not in restricted lane						
Junct. location of veh. at 1st impact	Mid junction - on roundabout or main road						
Veh left carriageway?	Did not leave carriageway						
Hit object in c'way?	None						
Hit object off c'way?	None						
First point of impact	Back						
Veh registration no.		Other veh.hit (ref.no)	1	Hit and run	Not hit and run		
Drivers age	? yrs	Breath test	Driver not contacted	Driving Lic			
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						

SEVERITY SLIGHT		District Kirklees Ref.No 110197939		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414087 / 412013 Police Officer Attend: Yes	
Date	30/04/2011	Day	Saturday	Road	A6024	Location	Woodhead Road at Junction with Northgate, Huddersfield
Time	14:15	Weather	Fine without high winds	Description	V1 Travelled South on Woodhead Rd Towards Northgate, V2 Cyclist in the Opposing Direction. both Stopped at Red Traffic Signal. V1 of Accident Intended to Turn right into Northgate, V2 to Continue in North. V1 was Behind a Vehicle. V2 Likewise. Traffic Signals Change, Vehicle in Front of V2 Moves Off. Vehicle in Front of V1 Turned right and then V1 Turned right into the Path of V2 Causing a Collision.		
Road Surface	Dry	Street Lighting	Daylight	SITE DETAILS	CONTRIBUTORY FACTORS PARTICIPANT PROBABILITY		
Speed Limit	30 MPH	SPECIAL SITE CONDITIONS	405 Failed to look properly (Driver/Rider - Error)				
Carriageway	Single carriageway	CARRIAGEWAY HAZARDS	None				
Junction Detail	Crossroads						
Junction Control	Automatic traffic signal						
2nd Road Number	U						
Pedestrian Facilities	None within 50 metres						
	Pedestrian phase at traffic signal junction						
VEHICLES INVOLVED 2							
Veh.No. 1	Vehicle type Car	Make	Model	CASUALTIES INVOLVED 1			
Manoeuvre	Turning right			Cas No	1	Cas Class	Driver or Rider
Veh. direction from	Northeast to Southwest	Towing?	No tow or articulation	Severity	SLIGHT	Age	53 yrs
Skidded	No skidding, jack-knifing or overturning			Car Passenger?	Not a passenger	Sex	Male
Veh location at impact (restricted lane)	On main carriageway not in restricted lane			Seat Belt	Not applicable	PSV Passenger?	Not a passenger
Junct. location of veh. at 1st impact	Leaving main road			Ped Movement	Not applicable	Cycle Helmet	
Veh left carriageway?	Did not leave carriageway			Ped Location	Not applicable		
Hit object in c'way?	None			Ped Direction to	Not applicable		
Hit object off c'way?	None			School Pupil	Other		
First point of impact	Front			Roadworker injured			
Veh registration no.		Other veh.hit (ref.no)	2	<u>Other Details</u>			
Drivers age	50 yrs	Breath test	Negative				
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						
Veh.No. 2	Vehicle type Pedal Cycle	Make	Model				
Manoeuvre	Going ahead other						
Veh. direction from	South to North	Towing?	No tow or articulation				
Skidded	No skidding, jack-knifing or overturning						
Veh location at impact (restricted lane)	On main carriageway not in restricted lane						
Junct. location of veh. at 1st impact	Mid junction - on roundabout or main road						
Veh left carriageway?	Did not leave carriageway						
Hit object in c'way?	None						
Hit object off c'way?	None						
First point of impact	Front						
Veh registration no.		Other veh.hit (ref.no)	1				
Drivers age	53 yrs	Breath test	Not Applicable				
Left Hand Drive	Unknown	Foreign veh.	Not foreign registered vehicle				
Journey purpose	Other						


SEVERITY SLIGHT		District Kirklees Ref.No 110548158		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414207 / 412064 Police Officer Attend: Yes	
Date 23/11/2011	Day Wednesday	Road U	Location Station Road 50 Metres East of New Mill Road, Holmfirth				
Time 15:30	Weather Fine without high winds	Description V1 Had Been Travelling in Station Road from New Mill Road. Whilst V1 was Travelling up a Slight Gradient Numerous School Children of Accident Were Walking in Station Road in the Opposite Direction to V1 at its Nearside. Cas1 a Pedestrian Stepped from the N/S Pavement Walking Directly into the N/S of V1. a Collision Occurs.					
Road Surface Dry	Street Lighting Daylight	SPECIAL SITE CONDITIONS None		CONTRIBUTORY FACTORS 802 Failed to look properly (Pedestrian)		PARTICIPANT PROBABILITY Casualty 001 A	
Speed Limit 30 MPH		CARRIAGEWAY HAZARDS None					
Carriageway Single carriageway							
Junction Detail Not at or within 20 metres of junction							
Junction Control							
2nd Road Number							
Pedestrian Facilities None within 50 metres							
No physical crossing facility within 50 m							
VEHICLES INVOLVED 1							
Veh.No. 1	Vehicle type Car	Make	Model	CASUALTIES INVOLVED 1			
Manoeuvre Going ahead other				Cas No 1	Cas Class Pedestrian	Veh ref No 1	
Veh. direction from Southwest to Northeast	Towing? No tow or articulation			Severity SLIGHT	Age 13 yrs	Sex Female	Post code
Skidded No skidding, jack-knifing or overturning				Car Passenger? Not a passenger	PSV Passenger? Not a passenger		
Veh location at impact (restricted lane) On main carriageway not in restricted lane				Seat Belt Not applicable	Cycle Helmet Cycle Helmet		
Junct. location of veh. at 1st impact Not at or within 20m of junction				Ped Movement Crossing from driver's nearside			
Veh left carriageway? Did not leave carriageway				Ped Location In carriageway, crossing elsewhere			
Hit object in c'way? None				Ped Direction to Southeast bound			
Hit object off c'way? None				School Pupil Yes on way to or from school			
First point of impact Nearside				Roadworker injured Not applicable			
Veh registration no.	Other veh.hit (ref.no) 0	Hit and run	Not hit and run	<u>Other Details</u>			
Drivers age 17 yrs	Sex Male	Breath test Negative	Driving Lic				
Left Hand Drive	Unknown	Foreign veh. Not foreign registered vehicle					
Journey purpose	Other						
Full Details							
28-August-2015							
Accident Ref.No 110548158							

SEVERITY SLIGHT		District Kirklees Ref.No 130067943		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414087 / 412012 Police Officer Attend: Yes	
Date 14/02/2013 Time 17:00	Day Thursday	Road U	Location Eastgate at Junction with Woodhead Road, Huddersfield				
Weather Fine without high winds Road Surface Wet/Damp Street Lighting Dark: street lighting unknown	Description V1 (Pedal Cycle) Travels Along Woodhead Road to Jw Eastgate and Starts to Turn right into Same. V2 Travelling to Rear of V1 Also Turn of Accident right from Woodhead Road into Eatgate. Whilst Making Turn V2 Collides with Rear Wheel of V1 Causing Rider to Fall from Vehicle Receiving Injury.						
SPEED LIMIT 30 MPH		SPECIAL SITE CONDITIONS None		CONTRIBUTORY FACTORS 405 Failed to look properly (Driver/Rider - Error) 406 Failed to judge other person's path/speed (Driver/Rider - E Vehicle 002 A		PARTICIPANT PROBABILITY Vehicle 002 A	
JUNCTION CONTROL Automatic traffic signal		CARRIAGEWAY HAZARDS None					
2nd Road Number A6024							
Pedestrian Facilities None within 50 metres No physical crossing facility within 50 m							
VEHICLES INVOLVED 2							
Veh.No. 1 Manoeuvre Turning right		Vehicle type Pedal Cycle		Make Model		Cas No 1	
Veh. direction from North to West		Towing? No tow or articulation		Age 42 yrs		Sex Male	
Skidded No skidding, jack-knifing or overturning		Veh location at impact (restricted lane) On main carriageway not in restricted lane		Car Passenger? Not a passenger		PSV Passenger? Not a passenger	
Junct. location of veh. at 1st impact Mid junction - on roundabout or main road		Veh left carriageway? Did not leave carriageway		Seat Belt Not applicable		Cycle Helmet	
Hit object in c'way? None		Hit object off c'way? None		Ped Movement Not applicable			
First point of impact Back		Other veh.hit (ref.no) 2		Ped Location Not applicable			
Veh registration no. 42 yrs		Sex Male		Ped Direction to Not applicable			
Left Hand Drive Unknown		Breath test Not Applicable		School Pupil Other			
Journey purpose Other		Foreign veh. Not foreign registered vehicle		Roadworker injured			
<u>Other Details</u>							
Veh.No. 2 Manoeuvre Turning right		Vehicle type Car		Make Model		Cas No 1	
Veh. direction from North to West		Towing? No tow or articulation		Age 42 yrs		Sex Male	
Skidded No skidding, jack-knifing or overturning		Veh location at impact (restricted lane) On main carriageway not in restricted lane		Car Passenger? Not a passenger		PSV Passenger? Not a passenger	
Junct. location of veh. at 1st impact Mid junction - on roundabout or main road		Veh left carriageway? Did not leave carriageway		Seat Belt Not applicable		Cycle Helmet	
Hit object in c'way? None		Hit object off c'way? None		Ped Movement Not applicable			
First point of impact Front		Other veh.hit (ref.no) 1		Ped Location Not applicable			
Veh registration no. 63 yrs		Breath test Negative		Ped Direction to Not applicable			
Left Hand Drive Unknown		Foreign veh. Not foreign registered vehicle		School Pupil Other			
Journey purpose Other		Foreign veh. Not foreign registered vehicle		Roadworker injured			
<u>Other Details</u>							

SEVERITY SLIGHT		District Kirklees Ref.No 13N0323		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414066 / 412275 Police Officer Attend: Yes						
Date	23/03/2014	Day	Sunday	Road	A616	Location	A616 Huddersfield Road Honley					
Time	05:45	Weather	Fine without high winds Wet/Damp	Description	V1 is travelling along Huddersfield road at Honley in the direction of Holmfirth. V2 and V3 are stationary vehicles parked at the road side of Accident and un occupied. The location of the incident is in the middle of a set of temporary traffic lights. V1 appears to lose control and hits the back of V2 which pushes V2 on to the pavement and on to V3. V1 remains at the scene as does the driver. Minor injuries only at this time.							
Street Lighting	Dark: street lights present and lit	SITE DETAILS		CONTRIBUTORY FACTORS								
Speed Limit	30 MPH	SPECIAL SITE CONDITIONS		503 Fatigue (Driver/Rider - Impairment) Vehicle 001 A								
Carriageway	Single carriageway	CARRIAGEWAY HAZARDS										
Junction Detail	Not at or within 20 metres of junction	None										
Junction Control		None										
2nd Road Number												
Pedestrian Facilities	None within 50 metres											
	No physical crossing facility within 50 m											
VEHICLES INVOLVED 3												
Veh.No. 1	Vehicle type	Car	Make	Model	CASUALTIES INVOLVED 1							
Manoeuvre	Going ahead other	Towing?	No tow or articulation		Cas No	1	Cas Class	Driver or Rider	Veh ref No	1		
Veh. direction from	North to South				Severity	SLIGHT	Age	32 yrs	Sex	Male	Post code	
Skidded	No skidding, jack-knifing or overturning				Car Passenger?	Not a passenger			PSV Passenger?	Not a passenger		
Veh location at impact (restricted lane)	On main carriageway not in restricted lane				Seat Belt	Unknown			Cycle Helmet	Not a cyclist		
Junct. location of veh. at 1st impact	Not at or within 20m of junction				Ped Movement	Not applicable						
Veh left carriageway?	Did not leave carriageway				Ped Location	Not applicable						
Hit object in c'way?	Parked vehicle				Ped Direction to	Not applicable						
Hit object off c'way?	None				School Pupil	Other						
First point of impact	Front				Roadworker injured							
Veh registration no.		Other veh.hit (ref.no)	0	Hit and run	<u>Other Details</u>							
Drivers age	32 yrs	Breath test	Negative	Driving Lic								
Left Hand Drive	No	Foreign veh.										
Journey purpose	Other											
Veh.No. 2	Vehicle type	Car	Make	Model								
Manoeuvre	Parked											
Veh. direction from	Parked to Parked	Towing?	No tow or articulation									
Skidded	No skidding, jack-knifing or overturning											
Veh location at impact (restricted lane)	On main carriageway not in restricted lane											
Junct. location of veh. at 1st impact	Not at or within 20m of junction											
Veh left carriageway?	Left carriageway nearside											
Hit object in c'way?	Parked vehicle											
Hit object off c'way?	None											
First point of impact	Back											
Veh registration no.		Other veh.hit (ref.no)	0	Hit and run								
Drivers age	? yrs	Breath test	Not requested	Driving Lic								
Left Hand Drive	No	Foreign veh.										
Journey purpose	Not Known											

Veh.No.	3	Vehicle type	Car	Make	Model
Manoeuvre	Parked				
Veh. direction from	Parked to Parked	Towing?	No tow or articulation		
Skidded	No skidding, jack-knifing or overturning				
Veh location at impact (restricted lane)	On main carriageway not in restricted lane				
Junct. location of veh. at 1st impact	Not at or within 20m of junction				
Veh left carriageway?	Did not leave carriageway				
Hit object in c'way?	None				
Hit object off c'way?	None				
First point of impact	Back	Other veh.hit (ref.no)	0	Hit and run	Not hit and run
Veh registration no.		Breath test	Not requested	Driving Lic	
Drivers age ? yrs	Sex Not know	Foreign veh.			
Left Hand Drive	No				
Journey purpose	Not Known				

SEVERITY SERIOUS		District Kirklees Ref.No 1C40243		Brockholes Junctions 1,2,3 - 01/08/2010 to 31/07/2015		Grid Reference 414088 / 412018 Police Officer Attend: Yes	
Date 04/12/2014 Time 08:20 Weather Fine without high winds Road Surface Dry Street Lighting Daylight		Day Thursday		Road A6024 Location Junction of A6024 Woodhead Road and Eastgate		Description C001 a child stepped out into the road and a passing car V001 ran over her foot causing broken bones. V001 had already passed through of Accident the junction and was exiting the other side of the crossroads it had been stationary in the junction waiting for the car in front to turn right when the incident happened. Witnesses state the car driver could not have done anything and was moving at slow speed.	
SPEED LIMIT 30 MPH		SPECIAL SITE CONDITIONS None		CONTRIBUTORY FACTORS 802 Failed to look properly (Pedestrian)		PARTICIPANT PROBABILITY Casualty 001 A	
JUNCTION DETAIL Single carriageway Crossroads		CARRIAGEWAY HAZARDS None					
JUNCTION CONTROL Automatic traffic signal							
2nd ROAD NUMBER U							
PEDESTRIAN FACILITIES None within 50 metres Pedestrian phase at traffic signal junction							
VEHICLES INVOLVED 1				CASUALTIES INVOLVED 1			
Veh.No. 1 Vehicle type Car		Make		Model		Cas No 1 Cas Class Pedestrian Veh ref No 1	
Manoeuvre Going ahead other		Towing? No tow or articulation				Severity SERIOUS Age 12 yrs Sex Female Post code	
Veh. direction from South to North						Car Passenger? Not a passenger PSV Passenger? Not a passenger	
Skidded No skidding, jack-knifing or overturning						Seat Belt Not applicable Cycle Helmet Not a cyclist	
Veh location at impact (restricted lane) On main carriageway not in restricted lane						Ped Movement Crossing from driver's nearside	
Junct. location of veh. at 1st impact Cleared junction or waiting						Ped Location On ped. crossing facility	
Veh left carriageway? Did not leave carriageway						Ped Direction to East bound	
Hit object in c'way? None						School Pupil Other	
Hit object off c'way? None						Roadworker injured Not applicable	
First point of impact Nearside						<u>Other Details</u>	
Veh registration no.		Other veh.hit (ref.no) 0		Hit and run Not hit and run			
Drivers age 51 yrs Sex Female		Breath test Negative		Driving Lic			
Left Hand Drive No		Foreign veh.					
Journey purpose Not Known							
Full Details				28-August-2015			
				Accident Ref.No IC40243			



© Crown Copyright and database right 2015
Ordnance Survey 100019241



Streetscene & Housing
Flint Street, Fartown
Huddersfield, HD1 6LG

20010492 Brockholes
Junction 5 Frontage

Accident data
01-08-2010 to 31-07-2015

Scale

NTS

Drawn
PW

Checked

Section
Safety

Date
Aug 15

Drawing No.

SEVERITY SLIGHT		District Kirklees Ref.No OBT1098		Brockholes Junction 5 Frontage - 01/08/2010 to 31/07/2015		Grid Reference 414245 / 408159 Police Officer Attend: No - reported over the counter	
Date Time Weather Road Surface Street Lighting	29/11/2013 16:20 Fine without high winds Dry Daylight	Road A635 Location Junction of A635 Victoria Street and B6106 Dunford Road		Description V1 is turning right from Victoria Street onto Dunford Road when a young girl runs across the road at the same time. DV1 brakes to a standstill and the girl runs into the side of the car. Girl already has ongoing medical issues with her feet which are exacerbated by the contact with the car.			
SITE DETAILS		SPECIAL SITE CONDITIONS		CONTRIBUTORY FACTORS		PARTICIPANT PROBABILITY	
Speed Limit Carriageway Junction Detail Junction Control 2nd Road Number Pedestrian Facilities	30 MPH Single carriageway T or staggered junction Give way or uncontrolled B6106 None within 50 metres No physical crossing facility within 50 m	None CARRIAGEWAY HAZARDS None		802 Failed to look properly (Pedestrian) 808 Careless/Reckless (Pedestrian)		Casualty 001 A Casualty 001 A	
VEHICLES INVOLVED 1				CASUALTIES INVOLVED 1			
Veh.No. 1 Manoeuvre Veh. direction from Skidded Veh location at impact Junct. location of veh. at 1st impact Veh left carriageway? Hit object in c'way? Hit object off c'way? First point of impact Veh registration no. Drivers age Left Hand Drive Journey purpose	Vehicle type Car Turning right West to South No skidding, jack-knifing or overturning On main carriageway not in restricted lane Leaving main road Did not leave carriageway None None Nearside	Make Towing? No tow or articulation	Model	Cas No 1 Severity SLIGHT Car Passenger? Seat Belt Ped Movement Ped Location Ped Direction to School Pupil Roadworker injured	1 Age 10 yrs Not a passenger Not applicable Crossing from driver's nearside In carriageway, crossing elsewhere West bound Other Not applicable	Veh ref No 1 Post code PSV Passenger? Cycle Helmet Not a passenger Not a cyclist	
Other veh.hit (ref.no) 0 Breath test Foreign veh. Driver not contacted		Hit and run Not hit and run Driving Lic					
<p>Full Details</p> <p style="text-align: right;">28-August-2015</p> <p style="text-align: right;">Accident Ref.No OBT1098</p>							

SEVERITY SLIGHT		District Kirklees Ref.No 10EA0481755		Brockholes Junction 5 Frontage - 01/08/2010 to 31/07/2015		Grid Reference 414255 / 408149 Police Officer Attend: Yes	
Date 11/11/2010 Day Thursday Time 08:00 Weather Raining with high winds Road Surface Wet/Damp Street Lighting Daylight		Road B6106 Location Dunford Road Jw Victoria Street, Holmfirth		Description V1 Slows for Bus to Pull out on Dundford Road. V2 Travelling Behind Collides at Slow Speed with Rear of V1. of Accident			
SITE DETAILS Speed Limit 30 MPH Carriageway Single carriageway Junction Detail T or staggered junction Junction Control Give way or uncontrolled 2nd Road Number A635 Pedestrian Facilities None within 50 metres No physical crossing facility within 50 m		SPECIAL SITE CONDITIONS None CARRIAGEWAY HAZARDS None		CONTRIBUTORY FACTORS 308 Following too close (Driver/Rider - Injudicious) 509 Distraction in vehicle (Driver/Rider - Impairment)		PARTICIPANT PROBABILITY Vehicle 002 B Vehicle 002 B	
VEHICLES INVOLVED 2		CASUALTIES INVOLVED 1					
Veh.No. 1 Vehicle type Car Manoeuvre Going ahead other Veh. direction from North to North Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Approaching junction or waiting Veh left carriageway? Did not leave carriageway Hit object in c'way? None Hit object off c'way? None First point of impact Back Veh registration no. Other veh.hit (ref.no) 2 Hit and run Not hit and run Drivers age 43 yrs Sex Female Breath test Not requested Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Other		Make Model Make Model		Cas No 1 Cas Class Driver or Rider Veh ref No 1 Severity SLIGHT Age 43 yrs Sex Female Post code Car Passenger? Not a passenger PSV Passenger? Not a passenger Seat Belt Not applicable Cycle Helmet Ped Movement Not applicable Ped Location Not applicable Ped Direction to Not applicable School Pupil Other Roadworker injured <u>Other Details</u>			
Veh.No. 2 Vehicle type Car Manoeuvre Going ahead other Veh. direction from North to North Towing? No tow or articulation Skidded No skidding, jack-knifing or overturning Veh location at impact (restricted lane) On main carriageway not in restricted lane Junct. location of veh. at 1st impact Approaching junction or waiting Veh left carriageway? Did not leave carriageway Hit object in c'way? None Hit object off c'way? None First point of impact Front Veh registration no. Other veh.hit (ref.no) 1 Hit and run Not hit and run Drivers age 36 yrs Sex Male Breath test Not requested Driving Lic Left Hand Drive Unknown Foreign veh. Not foreign registered vehicle Journey purpose Other		Make Model Make Model					