

External Alterations to Outbuilding
Dog Grooming Studio
26 Walkley Terrace, Heckmondwike, WF16 0PA

A wooden front door has been removed and replaced with double glazed patio doors with two side windows (see photo titled Alterations 1)

An additional double glazed side window has been incorporated (see photo titled Alterations 2)

The veranda at the front of the outbuilding has been added (see photo titled Alterations 3)

A small wooden extension has been added to the rear (see photo titled Alterations 4)

The roof to the property is being refitted and broken/missing tiles replaced.

New guttering is to be fitted.

External PIR lighting is to be fitted.