



EARTH ENVIRONMENTAL
& GEOTECHNICAL

OUR REF: A1819-19 Proposal 7th February 2019

YOUR REF:

Matthew Woodward
Kirklees Council

7th February 2019

By Email (matthew.woodward@kirkless.gov.uk)

Dear Matthew,

Busker Lane, Scissett
Technical Queries

We have been requested by KDP Architects to liaise with you about the ground monitoring.

It is understood that you have noted depleted oxygen in some of the wells during monitoring. For your convenience I have attached the monitoring data.

The depleted oxygen is merely a function of the extended monitoring over ten minutes.

There is no viable source of ground gas on the site or in the surrounding area.

Our view is that therefore that is no need for any ground gas mitigation measures and a damp proof membrane is all that is required on this development.

Please do not hesitate to contact me should there be any further queries.

Yours Sincerely,

Adam Czarnecki BSc (Hons) FGS CGeol
Director
For and on behalf of Earth Environmental & Geotechnical Ltd

cc. David Bennett, KDP Architects, davidbennett@kdparchitects.com

Enc: Ground gas monitoring data.

**CONSULTING
ENGINEERS**

Geotechnical
Environmental
Ecology
Geology
Drainage
Mining

Earth Environmental &
Geotechnical Ltd
Houldsworth Mill
Business & Arts
Centre
Houldsworth Street
Stockport
SK5 6DA

Tel: 0161 975 6088

www.earthenvironmental.co.uk
info@earthenvironmental.co.uk

ALSO AT:

Bath Office
Kingsbury House
Kingsbury Square
Melksham
Near Bath
SN12 6HL
Tel: 01225 434237

Reading Office
9 Greyfriars Road
Reading
Berkshire
RG1 1NU
Tel: 0118 3704730

Edinburgh Office
Hudson House
8 Albany Street
Edinburgh
EH1 3QB
Tel: 0131 5641789

Earth Environmental &
Geotechnical Ltd
Registered Office:
Mentor House,
Ainsworth Street,
Blackburn, Lancashire,
BB1 6AY
Registered in England
No: 8436152

