

Site Inspection Report

Project:				New 3 storey detached house. Hazeldene, Stoney Bank Lane, New Mill, Holmfirth , West Yorkshire, HD9 7LZ					
Project No:			W75154			Project Manager:		Tony Turner	
Date:		11/12/2015		Time of inspection:		08:35am	Weather:		Wet
Inspections req'd:		07		Site Report No.		01	Temperature		°C
Inspection Plan:			% or stage of works complete			Action required by Project Manager		Yes / No	
Comm.	Founds	Oversite	DPC	Drains	Struct. Frame	Progress	Commissioning	Completion	Occupation
11/12/15	11/12/15								

Works commenced.

Strip foundation has commenced. The excavation is approximately 800mm wide x 1000mm down on to bedrock. The rock is shattered above the bedrock so some has collapsed into the trench.

Sam Mashiter
Manchester Office