





Above and below show the poor state of the rear door installation.





Above shows the door at the bottom of the stairs that requires replacement for fire safety.