



Photograph 11: Dense vegetation towards the northern end of the site, facing north.



Photograph 12: Dense vegetation towards the northwestern end of the site, facing north.



Photograph 13: Blanket of whole bricks at the surface towards northwestern end of the site.



Photograph 14: Long narrow stockpile of bricks within area of dense vegetation towards the north centre of the site, facing north.



Photograph 15: View from the tops of the stockpile of bricks in photograph 14.



Photograph 16: Concrete slab within a clearing on northeastern end of the site.