



Planning ref 23/92542- Quaker Bottom

Photograph labelled number 1 shows the central dividing stone 1.2 metres by 1.5 metres. This is to be replaced with an exact matching stone.

Photograph labelled number 2 shows the flat horizontal stone which is 0.6metres by 1.2metres. This is to be replaced by an exact matching stone.

Photograph labelled number 3 shows a gap following the removal of the stone for inspection reasons. The original stone is in good condition and will be replaced in situ.

Photograph labelled number 4 shows the broken gatepost at ground level. The proposal is to replace with a 70mm wider post giving more strength to combat the lateral pressure from the embankment.