

Your ref [redacted]

Our ref 09499GLOB

Geo-Serv Limited
17 Hoveden Road
London NW2 3XE

tel: 020 8208 0343

email: mon@geo-serv.com

**Subsidence
Monitoring
Services**



GEO-SERV

360Globalnet Ltd
Bramley House,
Bramley Road,
Long Eaton,
NG10 3SX

Issue date: 15/01/2024

Monitoring visit 3 of 6

Monitoring Plus Report

Owners name	Mr. & Mrs. Doherty	Suspected cause	to be advised	Monitoring type	levels
Address	18 The Green Huddersfield HD2 1QB	Principal area of damage	to be advised	Installed	23/06/2023
Comment		Damage category	to be advised	Frequency (weeks)	8.7
Max movement	9.4 mm	Surface geology	to be advised	Completion date	Apr 24
Focal area	Pts 3, 4, 5, 6,	Feedback from last visit		Status	open
no comment for this visit		no feedback for this visit			
		Sketch showing location of monitoring points			
		<p style="text-align: center;">Front Elevation</p>			

Level Monitoring Results

Survey:	1		2		3		4		5	
By:	RW		BL		RW		#N/A		#N/A	
Date:	23/06/2023		18/09/2023		15/01/2024		#N/A		#N/A	
Point ID	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>
1	1000.00	0.0	1000.00	0.0	1000.00	0.0		#N/A		#N/A
2	924.71	0.0	925.02	0.3	924.75	0.0		#N/A		#N/A
3	1093.47	0.0	1089.99	-3.5	1098.26	4.8		#N/A		#N/A
4	1078.60	0.0	1073.52	-5.1	1082.58	4.0		#N/A		#N/A
5	771.39	0.0	765.94	-5.5	775.38	4.0		#N/A		#N/A
6	785.07	0.0	779.80	-5.3	787.86	2.8		#N/A		#N/A
7	789.97	0.0	786.52	-3.5	790.77	0.8		#N/A		#N/A

closing error (mm)

0.06


-0.15

0.16

#REF!

#REF!

Precise level monitoring related to Point 1



Photos from visit on 15/01/2024

