



## Ash Tree 1

Summary from Mr Mark Springfield of Springfield Tree Services in respect to granted tree works (application 2024/90412) and as per email sent to Mr Daniel Atkinson on 18<sup>th</sup> April 2024.

*Arrived at 34 Hyrst Garth, Batley, WF177AD this morning 18-04-2024 to perform granted tree works, on ascending to gain main anchor point I noticed the extent of damaged and dangerous branches, once these have all been removed there will not be much left of the tree and will probably not recover from the size of the wounds sustained, also main stem around 1.5-1.7m high damage and decaying cavities,*

*Please see supporting photos.*

*In my opinion it would be better to remove Ash and replant.*

*Rgs Mark*

*Springfield Tree Services*













