



**NOTES**  
It is the contractors responsibility to check design levels and sizes for compliance. Any discrepancies or errors to be identified to the design team.

**Key**

 Direction of Photograph

| REVISION | DETAILS | BY | DATE | CHECKED |
|----------|---------|----|------|---------|
|          |         |    |      |         |



info@sportslabsconsult.com

**EAST BIERLEY PLAYING FIELDS  
ACCESS ROAD DILAPIDATION  
CONSTRUCTION OF A NEW 3G PITCH**



|                   |                 |              |
|-------------------|-----------------|--------------|
| Date: 05/2024     | Job. No. 3255FF | Drawn by: CH |
| Scale: 1:500 @ A3 | Checked by: DD  |              |