

DISCLAIMER :  
 SURVEY BASED ON VISUAL INSPECTION OF SURFACE GROWTH. JKSL HOLD NO  
 LIABILITY FOR AREAS NOT IDENTIFIED IN INITIAL INVESTIGATION WORKS.  
 CONTINUED MONITORING OF SITE IS RECOMMENDED

-  AREA OF HIMALAYAN BALSAM SURFACE GROWTH
-  AREA OF MONTBRETIA SURFACE GROWTH
-  2M OR 3M RISK ZONE



SURVEY ORIENTATED TO MAGNETIC NORTH

|     |            |            |         |
|-----|------------|------------|---------|
| PH1 | 410773.720 | 417312.880 | 233.120 |
| PH2 | 410768.441 | 417323.980 | 233.020 |
| PH3 | 410778.875 | 417303.870 | 233.770 |
| PH4 | 410766.172 | 417322.580 | 233.240 |
| PH5 | 410785.301 | 417300.035 | 234.415 |
| PH6 | 410766.062 | 417300.061 | 233.620 |

| Rev | Description | Date | By | Chk |
|-----|-------------|------|----|-----|
|-----|-------------|------|----|-----|

Client  
 Lidl Great Britain Limited

Contract  
 New Hay Road, Huddersfield, HD3 4GP

Drawing  
 Japanese knotweed site inspection



|             |              |          |            |
|-------------|--------------|----------|------------|
| Drawing No. | JK24-9990-01 | Revision | /          |
| Scales      | NTS          | Date     | 13.08.2024 |
| Drawn       | AD           | Checked  | AD         |