



Paul Martin  
West End Joiners & Builders Ltd

# 785 - ST PAULS ROAD, MIRFIELD


---

3of3 Delap/Condition Survey documenting current condition  
of the ST PAULS CARRAIGEWAY from Junction of  
HUDDERSFIELD RD up ST PAULS RD to property identified as  
NO7

Tuesday 22 October 2024

# Client CONNECT HOUSING

85 Issues Identified



## LOCATION



## 1 / ST PAULS & HUDDERSFIELD RD JUNCTION



2



3



4



5



6



7



8



9



10



11



12



13



14



15



16



17



18



19



20



21



22



23




24




25




26




27




28



29




30




31



32




33



34




35



36



37



**38**



**39**



**40**



**41**



**42**



**43**



---

**44 / SITE ENTRANCE**



---

**45**



**46**



**47**



**48**



**49**



50




51



52



53



54



55



56



57



58



59



**60**



**61**



**62**



**63**



**64**



**65**



**66**



**67**



**68**



**69**



**70**



**71**



72




73



**74**



**75**



**76**



**77**




78




79



**80**



**81**



**82**



**83**

---

**84 / NO7 ST PAULS RD**

