Tree Hazard: Risk Evaluation and Treatment System (THREATS)

Hazard Location

ELR	MVL3	**Owner**	Network Rail
Mileage	020.1738	**Latitude**	53.622279
Trackside	Upside	**Longitude**	-1.886036
Distance to Rail (m)	21	**Distance to Third Party (m)**	2
Date of Survey	21/09/2023		

Tree Information

Tree ID	144384	**Species**	Broadleaf Sycamore
Tree or Group	Tree	**Number of Trees *(if group)***	
Age Class	Mature	**Size Category**	Very Large
Height (m)	15.3	**Diameter (mm)**	830
Description	At base of Viaduct ramp, opposite houses No.14,16&18, Howgate Road, Slaithwaite.	**Ash Class *(if Species Ash)***	

Risk Assessment

Survey Type	Full		**THREAT Type**	THREATS Non-Rail	
Failure Score	2.0	**Target Score**	40	**Impact Score**	10
Total Score	800		**Threat Category**	4: Moderate	
Defect Details	Overweight, Unstable root		**Action by Date**	21/12/2023	

Outline of Work Required

Work Required	Tree removal
Notes/Work Specification	Takedown tree using mechanical aids due to roofs adjacent and no suitable rigging points for timber. Road closure required. Footpath banksman/ footpath closure required. Resident notice required to move cars as narrow street. BT cables. Old tag no.582.