

NOTES

ORIGINAL A1

DO NOT SCALE FROM THIS DRAWING.  
ALL DIMENSIONS TO BE CHECKED ON SITE.  
COPYRIGHT PROTECTED.

Fire Risk Assessment Key Chart

- 1) All maintenance is completed by a competent contractor and records are held centrally.
- 2) All store testing routines are held in the opening and closing book.
- 3) All doors and walls to emergency staircases, corridors and partitions are built to minimum of 30 minutes fire resistance.

Equipment	Contractor Maintenance
W	Water Fire Extinguisher Annual
CO <sub>2</sub>	Carbon Dioxide Fire Extinguisher Annual
DP	Dry Powder Fire Extinguisher Annual
F	Foam Fire Extinguisher Annual
FB	Fire Blanket Annual
FP	Fire Panel 6 Monthly (Eire 4 monthly)
FS	Fire Shutter Annual or 6 Monthly
FC	Fire Curtain Annual or 6 Monthly
HR	Hose Reels Annual or 6 Monthly
DR	Dry Riser
EL	Emergency Lighting Internal & External Annual or 5 Monthly
FE	Fire Exit Sign
	Directional Signage
	Fire Alarm Call Point with Fire Panel Maintenance
	Yellow Break Glass Smoke Extract
	Green Break Glass
	Smoke Detectors 6 Monthly (Eire 4 monthly)
	Heat Detectors 6 Monthly (Eire 4 monthly)
	Sounder with Fire Panel Maintenance
	Sounder with Beacon with Fire Panel Maintenance
	Evacuation Chair

REV	DATE	DESCRIPTION	DRAWN	CHECKED
G 08/16		UPDATED AS PER RECEIVED PLANS	IMD	BELH
F 09/14		UPDATED AS PER RECEIVED PLANS	IMD	NB
E 08/13		UPDATED AS PER RECEIVED PLANS	IMD	MDH

CLIENT



PROJECT

Fire Risk Assessment

DRAWING

M&S Huddersfield  
Second Floor

CONSULTANT



CONSULTANT No	SCALE	DATE	DRAWN	CHECKED
1672	NTS	02/08/2016	BELH	
PROJECT No	DISCIPLINE	DRAWING No	STATUS	REV
1672		1672-2	G	

NB  
DRAWINGS BASED ON SCANNED ORIGINAL  
DRAWINGS ONLY. NOT A DIGITAL SURVEY  
ALL DIMENSIONS TO BE SITE CHECKED

