
Unit 1
Unit 2
Tarmac
Grass
Paved
Dense Vegetation
Scrub
Gravel
Bus Shelter
Gate
Car Sale area - Cars obscuring the ground
BLACKMOORFOOT ROAD
Boundary wall not visible due to trees
Conifer Hedge
Overhanging Canopy
Roof Level 197.19
Roof Level 202.49
Roof Level 203.40
Roof Level 200.81
Roof Level 201.41
Roof Level 202.11
Roof Level 202.21
Ridge Level 203.48
Eaves Level 201.71
Eaves Level 199.99
Ridge Level 197.63
Eaves Level 195.98
Ridge Level 198.55
Eaves Level 195.99
Eaves Level 203.62
Ridge Level 206.57
Eaves Level 203.58
Ridge Level 206.76
Eaves Level 203.55
Ridge Level 206.78
Eaves Level 203.59
Ridge Level 206.67
Roof Level 199.91
Roof Level 197.61
Top of Arched Roof 201.00
Eaves of Canopy
MH CL195.75
MH CL195.65
MH CL195.50
MH CL195.02
MH CL193.84
MH CL192.33
MH CL195.55
MH CL195.35
MH CL195.13
MH CL194.88
MH CL195.45
MH CL195.74
CL192.78
IC CL194.70
IC CL194.76
IC CL194.81
IC CL195.08
IC CL194.51
IC CL194.59
CL196.30
TEL
Slump
No Access
Flagpole
Flagpole
Stop
Toilet
Toilet
Toilet
Shed
Shed
Shed