

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 30m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 22m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 30m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 30m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 30m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 34m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged and misaligned.

Lower Fitzwilliam Street 45m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged and misaligned.

Lower Fitzwilliam Street 45m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 45m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 52m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged and misaligned.

Lower Fitzwilliam Street 52m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Drain partially blocked. Kerbs damaged and misaligned.

Lower Fitzwilliam Street 52m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged and misaligned.

Lower Fitzwilliam Street 50m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 50m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 57m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street 57m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged or misaligned.

Lower Fitzwilliam Street/ Southgate junction (west side at the lights)



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street/ Southgate junction (west side at the lights)



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged or misaligned.

Lower Fitzwilliam Street 62m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged or misaligned.

Lower Fitzwilliam Street 62m from lights



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged or misaligned.

Lower Fitzwilliam Street/ William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged or misaligned.

Lower Fitzwilliam Street/William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs damaged or misaligned.

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded.

Lower Fitzwilliam Street/ William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs opposite appear in good order.

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs opposite appear in good order.

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs opposite are damaged and misaligned

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs opposite are damaged and misaligned

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs opposite are damaged and misaligned

Lower Fitzwilliam Street / William Street (south west side) corner



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage.


Lower Fitzwilliam Street/William Street junction south side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage.

Lower Fitzwilliam Street/William Street junction south side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage.

Lower Fitzwilliam Street/William Street junction south side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage. Drain has minor debris build up inside.

Lower Fitzwilliam Street/William Street junction south side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage. Drain has minor debris build up inside. Vegetation growth to walkway.

Lower Fitzwilliam Street/William Street junction south side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage.

Lower Fitzwilliam Street/William Street junction south east side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Yellow and white lining faded. Kerbs showing signs of wear and minor damage.

Lower Fitzwilliam Street/William Street junction south east side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Vegetation growth to base of wall/path edge.

Lower Fitzwilliam Street/William Street junction south east side



Comments

Surface damage and scarring to footpath and carriageway from utilities works. Vegetation growth to base of wall/path edge.