

PLANNING AND LISTED BUILDING
CONSENT APPLICATIONS FOR
THE CHANGE OF USE AND INTERNAL
ALTERATIONS OF FIRST, SECOND
AND THIRD FLOORS TO FORM 5
APARTMENTS (WITHIN A
CONSERVATION AREA)

69-71 NEW STREET
HUDDERSFIELD
HD1 2BQ


APPENDIX ONE –
EXISTING PHOTOGRAPHS AND
ACCOMPANYING NOTES

PHOTOGRAPHS RELATE TO LOCATIONS IDENTIFIED ON PLAN 2388 / 02

FIRST FLOOR ROOM 1




PHOTOGRAPH 1 – Modern fixtures to be removed. Vertical Boarding added under window. Window Surrounds to Remain. Skirtings to be replaced.



PHOTOGRAPH 2 – Modern fixtures to be removed. Window Surrounds to Remain. Skirtings to be replaced.

FIRST FLOOR

ROOM 2



PHOTOGRAPH 3 – Modern fixtures and partitions to be removed.
Window Surrounds to Remain. Skirtings to be replaced.


ROOM 3



PHOTOGRAPH 4 – Modern fixtures and partitions to be removed.
Window Surrounds and Panelling to Remain. Skirtings to be replaced.

FIRST FLOOR

ROOM 4



PHOTOGRAPH 5 – Modern fixtures and partitions to be removed. Window Surrounds and Panelling to Remain. Skirtings to be replaced.

ROOM 5




PHOTOGRAPH 6 – Modern fixtures and partitions to be removed.

SECOND FLOOR

ROOM 7



PHOTOGRAPH 7 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain. Chimney Breast to Remain



PHOTOGRAPH 8 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain. Chimney Breast to Remain

SECOND FLOOR

ROOM 8



PHOTOGRAPH 9 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain.



PHOTOGRAPH 10 – Modern fixtures To be removed.
Door and Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain. Chimney Breast to Remain

SECOND FLOOR

ROOM 9



PHOTOGRAPH 11 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain. Chimney Breast to Remain




PHOTOGRAPH 12 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain.

SECOND FLOOR

ROOM 10




PHOTOGRAPH 13 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain. Chimney Breast to Remain.



PHOTOGRAPH 14 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Cornice and Picture Rail to Remain. Chimney Breast to Remain.

SECOND FLOOR

ROOM 11




PHOTOGRAPH 15 – Modern fixtures To be removed.
Window Surrounds to Remain.

THIRD FLOOR

ROOM 12



PHOTOGRAPH 16 – Modern fixtures To be removed.
Window Surrounds to Remain. Skirtings to be restored / replaced. Roof to be repaired.



PHOTOGRAPH 17 – Modern fixtures To be removed.
Skirtings to be restored / replaced.

THIRD FLOOR

ROOM 13



PHOTOGRAPH 18 – Modern fixtures To be removed.
Window Surrounds and Panelling to Remain. Skirtings to be restored / replaced.




PHOTOGRAPH 19 – Modern fixtures To be removed.
Window and Door Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Chimney Breast to Remain

THIRD FLOOR

ROOM 14



PHOTOGRAPH 20 – Modern fixtures To be removed.
Window and Door Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Chimney Breast to Remain. Roof to be repaired.



PHOTOGRAPH 21 – Modern fixtures To be removed.
Window and Door Surrounds and Panelling to Remain. Skirtings to be restored / replaced.
Chimney Breast to Remain. Roof to be repaired.

THIRD FLOOR

ROOM 15



PHOTOGRAPH 22 – Modern fixtures To be removed.
Window Surrounds Remain.



PHOTOGRAPH 23 – Modern fixtures To be removed.
Window and Door Surrounds Remain