

Condition 13 - Photographic Evidence of Parking and Access

Figure 1 – Google Maps screenshot of the site location with all three access points located to the west of the site.



Image 1 – Site visit image of one of the access points to the west of the site



Image 2 - Site visit image of one of the access points to the west of the site



Access point 1

Image 3 - Site visit image of one of the access points to the west of the site



Access point 2

Image 4 – Site visit image of one of the access points to the west of the site



Access point 2

Image 5 – Site visit image of one of the access points to the west of the site



Access point 3

Figure 2 – Google Maps screenshot of the parking to the south of the site



HGV Parking

Image 6 – Site visit image of parking to the south of the site



HGV Parking

Figure 3 – Google Maps screenshot of the parking to the west of the site



Image 7 – Site visit image of parking to the west of the site



Image 8 – Site visit image of parking to the west of the site



Parking

Image 9 – Site visit image of parking to the west of the site



Parking

Figure 4 – Google Maps screenshot of the parking to the north of the site



Parking

Image 10 – Site visit images of parking to the north of the site



Parking