

Rewiring and new fuse box

The submitted images show the existing fuse box prior to replacement and the new fuse box installed in the same location. The works were undertaken in a like-for-like manner, with no alteration to the surrounding historic fabric or finishes. The new installation complies with current electrical safety standards while remaining discrete and visually unobtrusive within the interior. No photographs of the wiring are available, as it is now concealed within the walls. Part of the reason for undertaking the rewiring was to address some plug sockets that were in the skirting boards (as shown in the photos), which did not comply with current building regulations. As the fuse box and wiring are modern service elements, the works have no impact on the special architectural or historic interest of the listed building, and all original features in the immediate vicinity have been retained intact.

Before



After

