

Boiler Replacement

The submitted images show the newly installed boiler and its flue. No photographs of the previous boiler are available; however, the replacement was undertaken in the same location and orientation as the original, ensuring that the historic fabric of the building was not altered. The new boiler is fully compliant with current building regulations. The flue has been installed in the same position as the previous one, as shown in the “old and new” comparison images below, ensuring there has been no change to its alignment or external impact. The installation is fully reversible and discrete, with no effect on the building’s special architectural or historic interest.

Before



Now

See position of flue

