








Dismantling Methodology – Part 2b Item 4.6 – Record of elements to be retained for record purposes only. (Issue 03 – 21/01/2026).




The following schedule updates the indicative schedule noted in the Arup Methodology Document Ref: 151667-TSA-30-MVL3-REP-A-AR-012001 (HUDDERSFIELD STATION - Methodology for deconstructing, storing and reconstructing the Tea Rooms.

Where materials have been retained for record purposes they will be retained by the project team throughout the duration of the project. Where they cannot be incorporated into the completed works they will further assessed at the end of the project and where necessary disposed on in line with the agreed disposal strategy.

Building Internal

Ref:	Item Description	Photograph
Café – 01	<p>MDF buffet counter.</p> <p>Note: This is a modern chipboard melamine counter top (dated 2005).</p> <p>Dimensions of the countertop are shown on HPC Drawing Ref: HPCSK008.</p>	
Café – 02	<p>Cladding Type B Plywood sheet.</p> <p>Note: This cladding material is 12.5mm modern gypsum plasterboard. Samples have been retained for record purposes.</p>	
All Areas – 03	<p>Bricks from solid walls.</p> <p>Samples retained from perimeter foundations and sub-walls.</p>	

<p>All Areas – 04</p>	<p>Door thresholds.</p> <p>Thresholds discovered to be either concrete infill or part of the timber soleplate. All to be retained for record purposes.</p> <p>Photo shows door threshold into café area – timber severely degraded.</p>	
<p>Café – 05</p>	<p>Wall tiles (behind counter).</p> <p>Sample wall tiles taken from site – these are modern ceramic tiles (See Findings report for full details).</p>	
<p>All Areas – 07</p>	<p>Floor Tiles - Zone 5 (Café) Cream and white ceramic floor tiles.</p> <p>Size: 400x400mm</p> <p>Samples of all floor tile have been taken for record purposes.</p>	
<p>Ref:</p>	<p>Item Description</p>	<p>Photograph</p>
<p>All Areas – 08</p>	<p>Lath and Plaster Ceiling -</p> <p>Samples of the plaster and timber laths have been retained for record purposes.</p> <p>Profiles and a retained section from the plaster coving has also been retained for record purposes.</p>	

<p>Café - 09</p>	<p>Clock display arms</p> <p>The actuator arms for the clock that was installed in the café area has been retained for record purposes.</p> <p>See HPC Fine Note 25 for full details.</p>	
<p>All Areas – 10</p>	<p>Discovered items</p> <p>All of the items including bottles, wrappers and tickets that were discovered during the dismantling of the Tea Rooms has been retained for record purposes.</p> <p>See HPC File Note 19 for full details.</p>	
<p>Building External</p>		
<p>Ref:</p>	<p>Item Description</p>	<p>Photograph</p>
<p>External – 11</p>	<p>Heritage Posters</p> <p>Copies of all heritage posters that were discovered under the moder poster frames have been retained for record purposes.</p> <p>See HPC File Note 09 for full details.</p> <p>Options to be reviewed to determine whether these can be displayed within the Tea Rooms.</p>	
<p>External - 12</p>	<p>Pavement Light</p> <p>Salvaged from site and retained for record purposes.</p>	