


## S278 AGREEMENT WORKS

### MERAKI ALLIANCE: STAGE I ROAD SAFETY AUDIT.

**RESPONSE DATE: 05.06.26**

Ref	Repeat Stage 1 Road Safety Audit		Design Organisation response	Overseeing Organisation response	Agreed RSA action
	RSA Problem	RSA Recommendation			
2.1	<p><b>Location:</b> General to scheme  <b>Summary:</b>            Drivers could become confused if old road markings are not fully removed before the new markings are implemented</p>	<p>Ensure the existing carriageway markings are fully removed or that the carriageway is resurfaced.</p>	<p>Key added to dwg. 8392_040A to show existing road markings to be removed.</p>		
2.1	<p><b>Location:</b> Proposed development access  <b>Summary:</b>            Increase in cross path collisions or pedestrian collisions, due to obstructed visibility.</p> 	<p>Ensure that the visibility splay is achieved and is kept free of obstructions, in perpetuity by undertaking site clearance.</p>	<p>Dwg. 8392_040A shows 2.4m x 40m Visibility Splay achieved, with no obstructions.</p>		

