

Photo 1: Entrance lane to the site.



Photo 2: Image shows existing club building.



Photo 3: Image shows northern playing fields.



Photo 4: Image shows the centre and western area of the site.

Rogers Geotechnical Services Ltd

Offices 1 & 2, Barncliffe Business Park,
Near Bank, Shelley,
Huddersfield,

Job No:

C5680/25/E/8797

Site:

Newsome Panthers ARLFC,
Hall Bower Lane,
Huddersfield,
West Yorkshire,
HD4 6RN

Client:

Newsome Panthers ARLFC

ground investigation | drilling & excavation | insitu testing
laboratory testing & gas monitoring | engineering consultancy
surveying & flood risk assessments | training, CPD & expert witness
... delivered using our own drilling rigs / crews / soils lab / engineers