

Image 1 - Showing location of tree (marked in the red circle) between 12 Banks Road, HD7 4LX, and the Rising Sun, HD7 4QF



Image 2 - Tree



Image 3 - Showing tree roots overgrowing the dry-stone wall



Image 4 - Showing tree roots overgrowing the dry-stone wall and subsiding over / impacting fence location



Image 5 - Showing tree roots overgrowing the dry-stone wall and subsiding over / impacting fence location



Image 6 - Showing tree roots overgrowing the dry-stone wall and subsiding over / impacting fence location



Image 7 – Showing location of the fence post position of the old fence that was pushed / caused to lean by the tree roots and subsistence.



Image 8 – Showing line of the fence impacted by tree roots and subsistence.

