

EXISTING SITE PHOTOGRAPHS

Supporting information – existing condition



Photo 1 – Existing rear elevation, raised paved terrace and lower garden.



Photo 2 – Existing rainwater downpipe and rear wall.

The photographs show the existing raised paved terrace on which the proposed pergola will sit, together with the lower garden, retaining wall, steps and existing rainwater downpipe. No vegetation removal or new terrace/platform construction is proposed.

Photographs are supporting information and are not to scale.

EXISTING WIDER SITE CONTEXT - ROADSIDE PHOTOGRAPHS

Drawing 04 | Photographs supplied by applicant

Supporting information - views from the nearby public road



Photo 3 - Wider site context from the public road.
The application property is the furthest house down the hill on the left of the photograph.



Photo 4 - Additional view from further down the public road.
Existing trees and seasonal foliage partly obscure views towards the application property.

These photographs record the existing wider visual context. Existing trees and vegetation are retained; no vegetation removal is proposed as part of the pergola works.

Photographs are supporting information and are not to scale.